

CHAINS

Restored Corners:

Page ( 115 )

Quarter Section Corner 20+21 T3N, R10W, W.M.

Original:

Post From which gone

24" spruce N25°E 22 Lks.

15" spruce N60°W 11 Lks

Stump Decayed below Face. 36" Diam.

stump burned and decayed below scribe Marks. Found a slab of wood lying near. This stump with scribed 1/4s plainly visible. stump and slab were Hemlock. 24" Diam.

Restored Corner:

Set a 3/4" x 36" G.I. pipe, From which,

Root of 5' spruce stump S82°W 22.5 Ft.

Scribed 1/4 S E. No live trees nearby.

Feb 27, 1951

Section Corner  $\frac{17}{20} \frac{16}{21}$  T3N R10W W.M.

Original:

Post, From which,

108" spruce N52°E 34 Lks

8" Hemlock N30°W 170 "

8" " S48°W 14 "

10" spruce S52°E 9 "

gone. Found an old Flat Iron bar in proper place.

Rotted down below Face gone.

3' Hem stump in place. No Marks.

This is a down 18" Hemlock with scribe Marks plainly visible in freshly chopped out Face.

Restored Corner:

Set 3/4" x 36" G.I. Pipe beside

BOOK 2 Old bar, From which,

15" spruce N33°E 52° ft scribed 1/4 S

115

Feb 13, 1951

