



UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
District Office
3550 Liberty Rd., S. E.
Salem, Oregon

IN REPLY REFER TO:
14.5 LJM
Engineering-9
Surveys

NOV 28 1961

County Surveyor
Tillamook County Courthouse
Tillamook, Oregon

Dear Sir:

We have given one of our contractors permission to high stump two bearing trees to keep them from blowing over. The corner involved fell in the middle of a clear cut area on one of our sales. High lead logging across the corner would have destroyed all evidence.


Enclosed is a description of the bearing trees which were cut.

Sincerely yours,

C. J. Krueger

BOOK 2

REPORT ON
CORNERS OF THE CADASTRAL SURVEY GRID
T. 15 R. 9W Will. Mer., Oregon State.



SYMBOLS

- ◆ Official corner found.
- ◇ Corner found, authenticity doubtful.
- Corner searched for and not found.

DESCRIPTION OF CORNER MONUMENT.

BLM brass cap and pipe

DESCRIPTION OF BEARING TREES, MOUND OF STONE, ETC.

537
fir stump 40", S44 1/4° E, 12 x 1 1/2,
fir stump 26", N56° W, 25 Lbs.
fir " 71", N58° E, 25 Lbs. (original)
" " 23", N15 1/2° W, 16 Lbs. (original)

DESCRIPTION OF LOCATION TO ENABLE RECOVERY BY OTHERS.

Reported By *Gregory Martin*
Title _____
Date 11-17-61

GPO 82-800094

BOOK 2

537

537