

TOWNSHIP PLAT NO. 279

For Sale by Kilham Stationery & Printing Co., Portland, Oregon

Township No. 6 South Range 9 West E. W. M.
Tillamook County, Oregon

<i>k</i>	6	5	4	3	2	1
<i>k</i>	7	8	9	10	11	12
	18	17	16	15	14	13
	19	20	21	22	23	24
	30	29	28	27	26	25
	31	32	33	34	35	36

Numbers in circle indicates classification of corners as of 7-12-10.

- ① - Original corner - An existent corner, verified by evidence of bearing trees or testimony.
- ② - Restored obliterated or reestablished lost corner by party other than L.P.Co.
- ③ - Restored obliterated corner by L.P.Co.
- ④ - Reestablished lost corner by L.P.Co.
- ⑤ - Established subdivision corner by L.P.Co.

TOWNSHIP PLAT NO. 278

For Sale by Kilham Stationery & Printing Co., Portland, Oregon

Township No. 6 South Range 9 East E. W. M.
Tillamook County, Oregon

②	6	5	4	3	2	1
	<i>Washill County</i> <i>Tillamook County</i>					
①	7	8	9	10	11	12
	18	17	16	15	14	13
	<i>Tillamook County</i> <i>Lincoln County</i>					
	19	20	21	22	23	24
	30	29	28	27	26	25
	31	32	33	34	35	36

CHAINS	
--------	--

Township 6 South Range 9 West

1. Section corner $\frac{21}{28}$ T. 6 S R 9 W. We set an iron pipe for the original Section corner 21, 22, 27 and 28. We put a tag on the original hemlock B.T. which bears N 54° E 38 lks., and on the original alder B.T. which bears N 18° W 26 lks. The hemlock is in good shape and the alder is in fair shape. The alder in the southwest quadrant is standing but dead. The scribe is visible. The alder in the southeast is down with the face rotted out.

J. M. Anliker
V. D. Thomas
4-30-54

2. 1/4 corner on north side of Section 28, T. 6 S R 9 W. We found the original closing 1/4 corner for section 28 on the line between sections 21 and 28. The original 30" spruce stump cut within the last few years is now 48". The 100' spruce is now down, and all scribe marks are visible. We set an iron pipe at this corner and put up a yellow tag on the 48" stump and a tag 100' west on a cat road. This corner is in dense hemlock and spruce reprod.

J. M. Anliker
V. D. Thomas
4-30-54

3. Sec. corner $\frac{20}{29}$ T. 6 S R 9 W. We set an iron pipe at the section corner and put up a tag on the road 40 feet east. The B.T.'s. are in bad shape as both are down. The scribe is gone in one and very little visible in the other. There are no trees to scribe.

J. M. Anliker
V. D. Thomas
4-30-54

4. 1/4 corner $\frac{28}{33}$ T. 6 S R 9 W. Found 2 original B.T.'s. for 1/4 corner $\frac{28}{33}$ T. 6 S R 9 W. Hemlock B.T. to the N.E. is now a blowdown. Scribe shows plainly. B.T. to the S.E. checks in bearing and distance but is a fir instead of a hemlock as called for in the original notes. The fir B.T. shows the overgrown face. We did not open this tree. Set an iron pipe for 1/4 corner and referenced as follows:

22" fir S 21° E 25.7' 1/4 S 33 B.T. Yellow tag
24" fir N 66° E 31.4' 1/4 S 28 B.T. " "

Scribed by: O. R. Miller of LFCo.
Witness: J. Anliker, J. Rodgers,
V.D.B. Thomas, June 15, 1954

Var. 21° 30'

5. 1/4 corner $\frac{21}{28}$ T. 6 S R 9 W. Found 2 original B.T.'s. for 1/4 corner. Set an iron pipe for 1/4 corner and referenced as follows:

4" hemlock S 79° E 13.5' 1/4 S 28 B.T.
36" spruce S 43° W 26.1' 1/4 S 28 B.T.

Scribed by: O. R. Miller of LFCo. & J. Anliker
Witness: J. G. Rodgers, all of LFCo.
V.D.B. Thomas June 15, 1954

Var. 21° 30'

No. 1-3-4