

CHAINS

Page 8. T.3-4SR10W. Evaluation and Restoration of Land Section corners

$\frac{1}{4}$ Secs. $\frac{31}{6}$ T3E $\frac{1}{4}$ corner between secs. 31-6
T4S

Original Monument:

4"x4" Fir post

Original Witnesses:

60" Hemlock; N.58°W., 38 lks.
4" Maple, S.10°E., 48 lks.

The original post and witnesses are gone. A 30" spruce marked by Billy Anderson, Tilla. Co engineer, bears S.9°W., 18 $\frac{1}{2}$ ft. with visible marks $\frac{1}{4}$ S. Billy Anderson testified to the fact that he saw one of the original witness trees at this corner and he marked the 30" spruce mentioned above and set a iron shaft at point for the corner, a logging operation caused the iron shaft to be buried or lost.

Therefore I set a 6"x6" spruce limb 24" high Mkd. $\frac{1}{4}$ S6 on S. side.

Also I set a 12x6x6 stone Mkd. x on top and $\frac{1}{4}$ on N. face. This stone is 12" beneath the ~~SW face~~ ^{SURFACE} of the ground on N. side of above post.

I marked 2 new BTs:

70" Spruce stump, S.12°30'E., 145ft. slope distance to scribed face of stump, Jkd. $\frac{1}{4}$ S6BT
102" Spruce stump, S.43°W., 223 ft. slope dist. to scribed face of stump Mkd. $\frac{1}{4}$ S6BT

Witness: B.P. Sheehan
by M. Whitmore,
Tilla. Co. Deputy Surveyor.
9-1-60

BOOK 3

BOOK 3