

CHAINS

Page 9.

EVALUATION AND RESTORATION OF LAND SECTION CORNERS
T.4.S.R.8.W.

$\frac{1}{4}$
7-8 $\frac{1}{4}$ corner between secs. 7-8
Original Monument
For a corner 52" fir Mkd. $\frac{1}{4}$ S on W. and E. faces.

Original Witnesses:
48" fir, S.84°E., 56 Lks. Mkd. $\frac{1}{4}$ S BT.
7" alder, N.74°W., 37 Lks. Mkd $\frac{1}{4}$ S Bt.

I found a 52" snag with scribe marks " $\frac{1}{4}$ S" on the East side and axe blazes on the W. and N. sides.

Found 16" alder, N.74°W., 37 Lks with a rotted out witness scar. Found 48" snag, S.84°E., 56 Lks. with all marks rotted off.

I bark scrobe the above mentioned original NW Alder $\frac{1}{4}$ S BT. and bark scribe a 18" Alder, N.77°E., 20ft. Mkd. $\frac{1}{4}$ S BT. This corner is 100ft. S. of the Powder Creek trail.

Witnesses: Hobart Means
M. Whitmore
by Leonard Whitmore
Tillamook Co. deputy surveyor.
9-4-61

EVALUATION AND RESTORATION OF LAND SECTION CORNERS
T4SR8-9W

R9 | R8
12 | 7
13 | 18
Original Monument
Post

Original Witnesses:
36" fir, N.12°W., 31 Lks. Mkd T4SR9WS12 BT
20" fir, N.31°E., 9 Lks Mkd. T4SR8WS7 BT
30" fir, S.24°E., 132 Lks Mkd. T4SR8WS18 BT
30" fir, S.80°W., 10 Lks Mkd T4SR9WS13 BT

I found the original post fallen upon the ground with a rock mound at its base. The four sides of the post are flattened but all marks are rotted away.

I found 36" snag, N.21°W., 31 Lks. with axe marks at its base and with visible but not legible scribe marks.

BOOK 3 The NE, SE and SW BTs are in their recorded bearings and