

CHAINS

T3S R9W

EVALUATION AND RESTORATION OF LAND SECTION CORNERS

One-quarter corner common to Sections 10-11, W.M., Till. Co., Ore

ORIGINAL: Original Post is gone.

Found 23" Alder, N.85°E., 23.1 ft. with original bark
Scribe $\frac{1}{4}$ " S BT.

Found 10" dead Alder Stub, N.20°W., 13.2 ft. with
original scribe $\frac{1}{4}$ " S BT.

This corner is located in a planned Timber Sale.
Future logging will destroy the two original
Alder Bts., therefore I mark 2 new Fir Bts.

RESTORED: Set $\frac{1}{2}$ " pipe 12" above ground. Mkd. a 4" x 4"
Fir limb post $\frac{1}{4}$ " on E-W sides. This post
sets alongside the pipe and is 2 $\frac{1}{4}$ " above ground.

I mark 2 new BTs. as follows:

32" Fir, S.37°E., 30 $\frac{1}{2}$ ft. Mkd. $\frac{1}{4}$ " S11CSBT.

30" Fir, N.89°W., 43 ft. Mkd. $\frac{1}{4}$ " S10CSBT.

Dated: 8-21-67

RESTORED BY: Leonard Whitmore, Till. Co. Deputy Surveyor

Approved for filing J. A. Kenton C.S.

WITNESSED BY: Max Carver