

County Surveyor's Record, Tillamook County, Oregon

CHAINS

(151) Re A-2711
Book 1, p 1

1/4 6/7 159

Found 1" Iron Pipe in Field
 4" Below Surface Badly Bent
 So I Followed The Pipe down to
 where it was straight in the Ground
 I Then Pulled it out & set a
 1 1/2" Iron Pipe in place of old Pipe
 16" Below Surface. So when Field
 is plowed it will Not Be Disturbed
 Old Bearing Tree Now Gone
 Because of Field.

8" Balm	S30W	43 ⁵⁶	} OLD BT'S New MISSING
80" Spr	S11E	66 ⁰⁰	
24 Spr	N49E	268 ⁶²	

New B.O.s Are 1/2" Iron Pipe & Post

IP in N&S Fence Line; 4x4x48 White Ced
 Post 0⁵ North of Pipe
 S60E 27⁵⁸

This fence is on sly side of Rd. Way
 IP in E&W Fence Line, 4x4x48 White ced
 Post 0⁹ East of Pipe @ 90° Lt. Interior From
 outhor witness Pipe N30E 76⁸³

S.A. Skinner
 G. Arthur 2-27-67

BOOK 5