

SURVEY FOR  
LONGVIEW FIBRE COMPANY

SECTION 36, T5S, R10W

BY LONGVIEW FIBRE COMPANY

December 13, 1973

Map #701


Survey was made with Wild T-LAE theodolite and a 500 foot steel tape for the purpose of determining the East line of the  $W\frac{1}{2}$  of the  $W\frac{1}{2}$  of said Section 36.

The lost  $1/4$  corners were thoroughly searched for in vain several times during the previous 15 years.

At the standard section corner common to sections 35 and 36, found iron pipe with brass cap

Standard corner	T5S	R10W
	35	36

Restored by Bureau of Land Management in 1962, with a brass cap marked as illustrated:



From which I found the following new bearing trees:

40" Fir bears S 40° E 17.0 feet

44" Fir bears N 82° E 29.30 feet

FEET Thence North 89° 47' E along the township line  
524.0 Creek 10' wide, course North 20° East