

OREGON STATE PARKS AND RECREATION DIVISION
RESURVEY

NE¼ Section 12, T6S, R9W, W.M.
Tillamook County, Oregon
July 20, 1982

NARRATIVE (See Plat)

The purpose of this resurvey was to reset the NE 1/16 corner of Section 12, T6S, R9W, W.M. This was due to an error in the original set that was pointed out to us by a Highway Division survey crew which had been working in the area and tying various corners along the Salmon River Highway.

A control traverse was established with a Kern "K1-SE" one-minute theodolite and a Hewlett-Packard 3805 electronic distance measuring instrument.

The bearings were derived from the State Park survey "Subdivision of Section 12, T6S, R9W, W.M." dated 6-8-67.

The inverse of the NE corner sec. 12 and the C-E 1/16 was compared to the inverse from our 1967 plat and proportional factors for the southings and westings calculated. These were then applied to the inverse of the NE corner Sec. 12 and the NE 1/16 from the 1967 survey and a proportioned coordinate for the reset of the NE 1/16 was derived.

The NE 1/16 then was set from our control and the 1967 iron rod was removed and accessory information adjusted.

Corner Information

Var. 20½°

Closing Corner 1, 12, and 7

ORIGINAL:

Post (missing) found 1½" iron pipe
36" Fir N68°30'W 72 links
now badly rotted 42" stump
20" Fir S45°45'W 19 links
now 28" stump "9WS12" visible
24" Fir S45°E 35 links (missing)

RESTORED:

Set 5/8" x 30" iron pin 26" in ground, 1.05 feet East of Pipe
Set 4" x 4" x 48" white post 0.6 feet South of pin
16" Alder N64°W 69.1 feet, scribed "T6SR9WS1CCBT"
22" Fir S54°30'W 64.4 feet, scribed "T6SR9WS12CCBT"
Yellow Corner tag on 22" Fir BT

State Parks Crew Found:

a 5/8"x30" iron rod alongside a 4"x4" white post
a 2½" brass cap 0.10 ft. south and 1.05 ft. west marked "T6S T6S"
S1 R8W
S12 S7
R9W
1975
PE 1956

Three BT's and a stump also found.
Did not check out accessories to this corner.

Witnessed by: A. Slack
S. Doak
R. Lee