

OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT
Tillamook County Surveyor's Office

SECTION: Located in the NW 1/4 of Section 26	TOWNSHIP 1 South	RANGE 9 West	
COUNTY: Tillamook		DATE: 06-15-11	
CORNER DESIGNATION: The Northwest 1/16 corner of Section 26, Township 1 South, Range 9 West, W.M., Tillamook County, Oregon.		(Please check one)	
		<input type="checkbox"/>	Condition Report Only
		<input type="checkbox"/>	Restoration
		<input checked="" type="checkbox"/>	Rewitness
		<input type="checkbox"/>	Unrecorded
		<input type="checkbox"/>	Reset at surface
		<input checked="" type="checkbox"/>	Referenced Out
Previous Rewitnesses, Restorations and Surveys, etc.: See Tillamook County Rewitness card number 222, Tillamook County Rewitness Book 5, Page 206; survey maps C-202, A-180, A-1317, A-2140, A-2380, A-3031, A-3490, A-3970, A-4149, A-4419, A- 5859, A-7560, B-829, B-972, Tillamook County Survey Records.			
Found Monument(s) and Accessories (Condition & Source): Found a 3" diameter Tillamook County Surveyor Brass cap, in a 10" diameter tile and concrete. Monument was found to be in good condition. Found a 26" diameter Hemlock tree with a healed face and no tag at record position (was a 12" diameter hemlock tree scribed "S26BTC" that bears S 82° E 87.25 feet the record value from Rewitness Card number 222 - 1973). Found a 4" x 4" x 48" white cedar wood post nailed to a 6" x 6" fence post. The 4" x 4" post was found at record position (bearing South 14.5' the record value from Rewitness Card number 222 - 1973). Found power pole number 262705 which is the same power pole noted on Rewitness Card number 222 but is now renumbered from ES7-R8-26. The power pole is found with a scribed triangle and a nail set in the center of the triangle on the West side of the pole and is approximately 1.0' above the ground. The power pole was found to be at record position bearing S 2° E 13.9', the record value from Rewitness Card number 222 - 1973.			
Monument Restoration (Procedures and Description): The found monument was encased in a 10" diameter tile with concrete and at road surface. We referenced out the position of the found monument, broke off the concrete from around the monument and then drove the monument further into the ground to allow for the placement inside the new 10" diameter monument case.	Sketch of Found Monument:		
New accessories set: No new accessories were set.			
New Bearing Trees: No new bearing trees were set.			
Location & Comments: This corner is located approximately 25 feet South of a small creek that runs East-West through a culvert under the existing road and located at the corner of Hughey Lane County Road and Diamond Street, at the most Easterly terminus of Hughey Lane County Road.			
Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE		SURVEYOR'S SEAL	
Party Chief: Joe Jensen, PLS 60067, Survey Supervisor, Deputy County Surveyor		<div style="border: 1px solid black; padding: 5px; display: inline-block;"> REGISTERED PROFESSIONAL LAND SURVEYOR <i>Joseph V. Jensen</i> </div>	
Notes: Digital images were taken of the found monument and accessories.		<div style="border: 1px solid black; padding: 5px; display: inline-block;"> OREGON JANUARY 10, 2008 JOSEPH V. JENSEN 60067 </div>	
Witnesses: Danny R. McNutt, PLS 49230, Tillamook County Surveyor; Michael R. Rice, L.S.I. 16723, Survey Technician		RENEWAL DATE: 06-30- 2013	

