

CONTRA CORNER TAG AFFIXED

TILLAMOOK COUNTY REWITNESS #1 1111 #1

35	36
2	1

SEC. 35/36
COR. 2 11 T 1 & 2 N R 6 W., WM.

HISTORICAL: G.L.O. Pg. 12 IN 6 SET POST 1874


BOOK	PAGE	MAPS
1	154	FG T.C. POWERLINE MAPS

CONDITION GOOD FOUND 1 1/2" IRON PIPE WITH 3" O.S.B.F BRASS CAP

* FD NOW 20" FIR FACE OVERGROWN	6" FIR	S. 14° E. 38'	BOOK 1 PAGE 154
* FD NOW 22" FIR FACE OVERGROWN	6" FIR	S. 43° W. 46'	BOOK 1 PAGE 154
FD. SCRIBING VISIBLE	26" FIR STUMP	N. 15° W. 14'	BOOK 1 PAGE 154
* FD NOW 23" FIR FACE OVERGROWN	7" FIR	N. 53° E. 153'	BOOK 1 PAGE 154
FD. ROTTEN REMAINS	8" CEDAR	N. 31° E. 9 LKS.	G.L.O. Pg. 12
FD. ROTTEN REMAINS	8" CEDAR	S. 18° E. 25 LKS.	G.L.O. Pg. 12
FD. ROOT HOLE	6" CEDAR	N. 52° W. 14 LKS.	G.L.O. Pg. 12
FD. UP ROOT	15" CEDAR	S. 30° W. 43 LKS.	G.L.O. Pg. 12

REWITNESS

I SET 10" CONCRETE CYLINDER AROUND FOUND O.S.B.F. 1 1/2" IRON PIPE WITH 3" BRASS CAP. BK. 1 Pg. 154
* 84" Flat Section NORTH 15 FEET



NEW ACCESSORY:

COMMENTS: THIS CORNER IS LOCATED ± 500' NORTH OF THE POWER LINES & ± 500' WEST OF THE SAME POWER LINES.

IN THE PRESENCE OF: DAN MCNUTT AL DVORAK

DATE: JUNE 1988

PHOTO: 5/11/88 4-88 Allen Peterson
TILLAMOOK COUNTY TITLE

* = County corner tag affixed.