

TILLAMOOK COUNTY REWITNESS

276

N. 1016 SEC. 2
 1/4 COR. T 15 R 10 W., WM.
 S.

HISTORICAL: GLO Page 30-31

Book	Page	MAP
1	84	A-131
4	64	
"T-27"	125-127	

CONDITION


FOUND: 2" Iron Pipe BK 4 Page 64

Found STUMP ^{520°E} 22 1/2 TO FACE	64 Spr S20°E 35 IKS = 23 10	GLO
MISSING	24 Spr N12°E 52 IKS = 34 3E	GLO
	12" Alder S29°45'E 15° Feet	Book 1 Pg 84
	10" Alder N2°30'W 12° Feet	Book 4 Pg 64

Found corner by reproducing information shown
 COMMENTS: on C.S. MAP A-131 and on C.S. MAP B-229.

REWITNESS

1 SET 1 1/2" Iron Pipe with Brass Cap (GA/TB) SET CAP IN CONC. 1972 AND 10" TILE
 1 SET A 6" x 15" I.R. UNDER THE I.P. and replaced I.P.+RC



72" Hat Section S. 483
 6" ~~WIDE~~ BELOW Road Bed. Jfy 1980

NEW ACCESSORY:

		scribed
20" Hemlock	S42°E 89 3E	1/4 S11 BT CS

COMMENTS: Corner is ± 90 feet West of S.P.R.R. Tracks and located in a seldom used gravel road bed which extends westerly to the bay. Corner is tied to IDAVILLE COUNTY ROAD. REFER TO MAP B-229

IN THE PRESENCE OF: Geo W Urry
 Gale Arthur
 A. Duncan

DATE: 1968 & 1972 PHOTO#: _____ TITLE _____

* = County corner tag affixed.