


COPIED FROM 100 311190

TILLAMOOK COUNTY REWITNESS # 416



SEC. 28 T 25 R 9 W., WM.
 COR. S. E.
 MARCH 1950 A.S.B.F.

HISTORICAL: MAP B-404 Subdivision of Section 28

MAP A-808 John ^{RS-287} Louis Carlich - SET 1 1/2" Iron Pipe
MARKED ONE B.T. 18" Spruce NO°26E 36°


CONDITION Good FOUND: 1 1/2" Iron Pipe

Now 22" spruce Good * 18" Spruce NO°26E 36°	
B.T. CONDITIONS FOUND 6-17-1998 BELOW	
* 22" SPRUCE NO°26'E 36°; FOUND, NOW 34" SPRUCE FACE HEALED POSITION	
* 48" HEMLOCK N59°E 81 1/2. FOUND 74" SPRUCE @ POSITION, FACE HEALED, DO NOT CUT TAG ATTACHED.	

COMMENTS:

REWITNESS

1 SET 2" Iron Pipe with Brass Cap in tile & Cement



* ±90 " Hat Section		± 15 feet
NEW ACCESSORY:		
48" HEMLOCK * N59°E 81 1/2		

COMMENTS: Corner is located on county road that goes to Munson Creeks Falls Park. Corner is on south side of road ± 15 feet from road CENTERLINE AND located part way up the cut-back slope.

IN THE PRESENCE OF: Gale Arthur

DATE: 11-3-71

COB *
 PHOTO#: 2EC
 TITLE
 LIFTWOOD COUNTY REWITNESS

County corner tag affixed.