

CORNER RECORD (SEARCH) (Ref. PSM 7151.4) Tract or Survey No. Cor.

Index file No. A-13 R.D. HEBO County TILLA **#586**

Merid. W.M. N.F. SIUSLAW State ORE.

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND

GLC 1933 SET BRASSCAP-TRUE CORNER POINT IS
30" HEM, S. 53° E, 17 LKS. N. 3° 30' W. 10 FT. UNDER
22" SNAG, N. 53° W, 12 LKS. BLOW DOWN LOG.
32" HEM, S. 73° W, 7.3 LKS.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

FOUND 1 1/2" GALV PIPE IN POOR CONDITION. BRASSCAP
HAS RUSTED FROM THE PIPE.
A 4" X 4" X 36" WHITE POST SETS 1 FT. S. E.
FOUND 37" DEAD HEM, S. 53° E, 11 1/2 FT. WITH VISIBLE
SCRIBE MARKS. OTHER BT'S ARE GONE.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

SET IRON FENCE POST 1 FT. SOUTH.

PHOTO IDENTIFICATION DATA

Photo No. ETJ-9-45

Filed At

Object Ident. DIRECT.

Sent. By Signature

PLANE COORDINATE POSITION DATA

State Zone

Established By Agency

Signature Title Division Date

Leonard Whitmore Forestry tech Timber 2-28-76

REWITNESS

I SET "x" "x" " Post N.W. feet

 " Hat Section S. E.

NEW ACCESSORY:

COMMENTS:

IN THE PRESENCE OF:

DATE: PHOTO#: TITLE:

* = County corner tag affixed.