

TILLAMOOK COUNTY REWITNESS # 609  
 N. 1/16 COR. SEC. 11 T 35 R 10 W., WM.


HISTORICAL MAPS  
 A-1008 Subdivision of section  
 A-1196 Subdivision of NE 1/4 of section  
 A-1475 Subdivision of section

CONDITION	FOUND:	8" SPIKE	Bk	Page
OK	5/8" Iron Rod	North 12.65	5	127
OK	5/8" Iron Rod	South 28.35	5	127
OK	Power Pole	N 81° W 108.40	5	127
Replaced with Hat section	4x4 Post	North 12.0		
RESET: 5/8" IR. "NORTH	12.65" TO NORTH	20.30' DUE TO ROAD WORK		DA 2-24-92

COMMENTS:

REWITNESS

1 SET 1 1/4" Iron Bar with Brass Cap in Cement  
 N. feet



\* 96 " Hat Section NORTH 12.00  
 RESET TO NORTH 20.80 DUE TO ROAD WORK DA 2-24-92

NEW ACCESSORY:

"P.K." Nail	South	7.31	(PK)
"56" Nail	Northerly	1.27	(56)
"56" Nail	Easterly	1.18	(56)

COMMENTS: Removed Spike & Placed Iron Bar with Brass Cap for Corner.

IN THE PRESENCE OF: Roger Knippel G.W. Urrey  
 Dale ARTHUR  
 Al Duncan RS 793 M. MW.

DATE: December 1971 PHOTO # SEC  
 TILLAMOOK COUNTY DEPT OF ASSESSOR TITLE C.S.  
 \* = County corner tag affixed. G.W.U.