

WINDLO: SEC.
 1/4 COR. 17116 T 35 R 10 W., WM.
 E.17

HISTORICAL: GLO-- W. P. Wright 1882--Pages 38#39
 U. Jackson--1913--F-41-45 MAP F-24-17
 G. J. Paysky--1914-- F-40-58
 W. S. Coates--1920-- B-218 (SHEET No. 7)
 W. E. Anderson--1947-- B-97-- Shows Subdivision of Sec. 17
 W. E. Anderson--1926-- Field Notes-- BK 45 Page 67#68
 BK 48 Page 8 shows G.T.'s to 1/4 cor. Book 5 Page


CONDITION

GOOD	Bridge Spike Flush with Pavement
GOOD	4" x 4" x 48" WHITE POST With bearing tag
	Post bears 18 1/2' West of Corner
15' in open field	40" Spruce N 86° 28' W 55° BK 48 Pg 8
Remains at distance	24" Hemlock S 88° 29' E 72 ± BK 48 Pg 8

COMMENTS: Removed spike & set rebar

REWITNESS

1 SET 1/4" Rebar with 3" Brass Cap
 Post WEST 18 1/2 feet



96" Mat Section

NEW ACCESSORY:

Power Pole 121-B.E.	S 72° W 33°	△
* 4" Hemlock	N 79° E 48 ±	1/4 SIG BT CS
Power Pole 120-B.E.	N 12° E 138 ±	△

WE 4/21/70
 A.E. Urry

COMMENTS: CAP IS FLUSH WITH BLACKTOP SURFACING

Fd remains of 24" Hemlock at S 88° E 74 ± feet = Tree has fallen over

IN THE PRESENCE OF: George Urry
 Gale Arthur

DATE: 4-21-70 PHOTO: SEC 17/22/12
 COB: [Signature] TITLE

* = County corner tag affixed.