



3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners: **#636**

7. Photo Identification
 Photo No. _____
 Ident. By: _____

8. Plane Coordinate Position Data
 State: _____ Zone: _____
 X: _____
 Y: _____

Estab. B: _____
 Field Bok No. _____
 Where filed: _____

9. Evaluation
 Author: _____
 Needs Writ. Monument: _____
 Re-esta. Survey: _____
 Ad Situa. PATENTED - N.E.

5. Investigation Notes:
 FOUND A BROKEN STUB FOR CORNER IN POOR CONDIT-
 ION UNDER A BLOWN DOWN STUMP.
 FOUND 18 IN. SPLINTERED HEMLOCK STUB WITH VIS-
 IBLE MKS. S B N. 54° W., 13 FT.
 FOUND 12 IN. HEMLOCK, S. 19° W., 7.3 FT. WITH AVISIBLE
 MK. S.
 FOUND 22 IN. HEMLOCK, N. 40° E., 16 1/2 FT. WITH HEALED WIT-
 NESS SCAR.
 FOUND 18 IN. HEMLOCK STUMP, S. 65° E., 17 FT. WITH LOWER
 PART OF WITNESS BLAZE SHOWING.

6. Signed L. WHITMORE Title FORESTRY TECH Date 2-21-63

PERPETUATION RECORD

10. Monument: _____

11. Accessories
 Leonard Whitmore is a Deputy County Surveyor
 empowered to re-witness positive old evidence
 of 660 corners
 4/18/74 J. K. Co Surveyor

12. Set By _____ Title _____
 License _____ Agency _____ Date _____

13. Recorded By _____ Volume _____ Page _____
 (Date) (City) (County) (State)

14. Remarks: SET PIPE UNDER UPROOT.
 New BTs
 28 IN. HEMLOCK N. 75° E., 64 LKS. MKD. T3SR10WS 24BT
 38 IN. FIR, S. 43° 30' W., 68 LKS. MKD. T3SR10WS 26BT
 30 IN. FIR, N. 35° 30' W., 165 LKS. MKD. T3SR10WS 28BT
 NO TREES AVAILABLE IN SECTION 25