

43 R9W No. L13 Cor. 1/4 Mer. Will. State ORE. (Rectangular) N. F. SIUSLAW Dist. HEBO

2. Corner Status

3. Original Description Vol. Page Where Recorded #696

4. Description of Corners:
Rock mound with marked stone


5. Investigation Notes:
Find a man-made rock mound on steep west slope. Find the marked stone with visible S16 where it had rolled fifty feet down the slope to a bench.
Replace the marked stone at the rock mound and witness two trees

7. Photo Identification
Photo No. _____
Ident. By: _____

8. Plane Coordinate Position Data
State _____ Zone _____
X _____
Y _____
Estab. By _____
Field Book No. _____
Where Filed _____

9. Evaluation
Authentic
Needs Verif. Monument
Re-estab. Survey _____
and Status N.E.

6. Signed L. Whitmore Title Forestry aid Date 2-22-61



PERPETUATION RECORD

10. Monument: Original rock mound and marked stone

11. Possibilities: new BT's

2.8 in. fir, N. 26°30' E., 37 ft. scribed 1/4 S 15 BT
1.8 in. fir, S. 6°30' W., 18.5 ft. scribed 1/4 S 16 BT
put bearing tree signs on said BT's
Witness: M. Whitmore

12. By _____ Title _____ Agency _____ Date _____

13. Recorded By _____ (Agency) _____ Volume _____ Page _____
(Date) (City) (County) (State)

14. Remarks: