


COWW

REWITNESS

#919

I-SET



"x" "x" Post N.W. feet
Hat Section S.E.

NEW ACCESSORY:

COMMENTS: backside of front is blank

IN THE PRESENCE OF:

DATE:


PHOTO#

County corner tag affixed.

REWORK CORNER BEARINGS TITLE

T.S. 6 SR 11W No. 2-19-20 Cor. Merill State OR (Rectangular) N.F. SIVSLOW Dist. Hebo

Corner Status



MEANDER 2 CORNER

Photo Identification

Photo No. _____

Phot. By: _____

Plane Coordinate Position Data

Zone _____

Obs. By: _____

Field Book No. _____

Where Filed _____

Evaluation

Monument

Survey

Other _____

Status _____

3. Original Description Vol. Page Where Recorded

4. Description of Corners:

5. Investigation Notes:

FOUND 3"x3" LIMB FOR CORNER POST IN POOR CONDITION LYING UPON THE GROUND WITH AXE MARKS AT TOP OF POST.

FOUND 54" SPRUCE, N.54°E, 99 LKS. WITH HEALED WITNESS FACE. (ORIG)

FOUND 57" SPRUCE, S.22°E, 63 LKS. WITH HEALED WITNESS FACE. (ORIG)

THIS MEANDER CORNER IS THE MOST WESTWARD POINT ON THE FIRST STANDARD PARALLEL LOCATED ON TOP OF A BLUFF OVERLOOKING THE OCEAN.

6. Signed L. WHITMORE Title FORESTRY TECH Date 7-18-64