


INDEX File No. E-25 CORNER RECORD (SEARCH) (Ref. FSM 7151.4) TRACT OF Survey No. _____
 T. 6S R. 9W D. Hebo County TILLA State ORE. # 952
 Merid. WILL. N.F. SIUSLAW

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND
 1887 GLO SET POST & MKD;
 36" FIR, N. 68° 30' W., 72 LKS.
 20" FIR, S. 45° 45' W., 19 LKS.
 24" FIR, S. 45° E., 35 LKS.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
 FOUND 3/4" GALV. PIPE AND 4" X 4" WHITE POST 1 FT. EAST.
 FOUND ORIG. 24" ROTTED FIR STUMP, S. 45° 45' W., 12 FT
 DESCRIBE MARKS "9W12" SHOWING.

PHOTO IDENTIFICATION DATA

Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
 Signature _____
 PLANE COORDINATE POSITION
 State _____ Zone _____
 X _____
 Y _____
 Estab. By _____
 Agency _____


THE NW BT IS A ROTTED STUMP.
 THE SE BT IS MISSING.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
 I MARK ONE NEW BT;
 6" FIR, N. 44° W., 32 1/2 FT. TO SIDE CENTERED.
 SCRIBED "CCT65R9WS1BT".
 PUT BT SIGNS ON WITNESSES.

Signature: Leonard Whitmore Title: atst tech Division: Timber Headquarters: Hebo Date: 3-4-74 7100-52 (3/68)

REWITNESS

I SET _____ "x" _____ "x" _____ " Post N.W. _____ feet
 _____ " Hat Section S. E.



NEW ACCESSORY:

COMMENTS: Whitmore corner monument
replaced by 6" white post 1 ft east

IN THE PRESENCE OF: _____

DATE: _____ PHOTO# _____ TITLE _____

* = County corner tag affixed.