


LAND CORNER RECORD

T. 6S R. 9W No. E-3 Cor. 7 Mer. Will State ORE N. F. SILLSLAW Dist. Heb



3. Original Description _____ Vol. _____ Page _____ Where Recorded _____
 4. Description of Corners:

5. Investigation Notes: **#966**
 FOUND 1/2 IN. GALV. PIPE 1 1/2 FT. ABOVE GROUND.
 FOUND 30 IN. HEM. (ORIG) N. 30° W., 18 LKS. LYING UPON THE
 GROUND WITH VISIBLE MKS. 1/4 S 6 BT.
 FOUND 18 IN. FIR STUB (ORIG) S. 45° 30' W., 33 LKS. LYING UPON
 THE GROUND WITH VISIBLE MKS. 1/4 S 7 BT. 1943 - 1959
 LOCATION F.S. POSTERS ARE ON BOTH LOGS.
 THIS CORNER IS LOCATED IN THE CENTER OF A RECENT
 BLOWDOWN. I SCRIBE TWO WITNESS TREES OF WHICH
 ARE LARGE FIR SNAGS THAT I FEEL WILL NOT BE

Ident. By: _____
 B. Plane Coordinate Position Data
 State _____ Zone _____
 X _____
 Y _____
 Etab. By _____
 Field Book No. _____
 Where Filed _____
 9. Evaluation
 Authentic
 Needs Verif. _____ Monument
 Re-estab. _____ Survey _____
 Land Status P.O.

6. Signed L. WHITMORE Title FORESTRY TECH Date 12-27-62

PERPETUATION RECORD

10. Monuments: _____

11. Accessories
 LEONARD WHITMORE IS A DEPUTY COUNTY SURVEYOR EMPOWERED
 TO RE-WITNESS POSITIVE EVIDENCE OF OLD CORNERS.
 JLG:ncs 1/8/75

12. Set By _____ Title _____
 License _____ Agency _____ Date _____
 13. Recorded By _____ (Agency) _____ Volume _____ Page _____
 (Date) _____ (City) _____ (County) _____ (State) _____

14. Remarks:
 DESTROYED BY THE FUTURE LOGGING OF THIS BLOW-DOWN.
 CORNER IS ON A 15% EAST SLOPE 100 FEET WEST OF A ROAD.
 New BT°
 54 IN. FIR SNAG, S. 70° E., 17 LKS. MKD. 1/4 S 7 BT.
 53 IN. FIR SNAG, N. 11° E., 114 LKS. MKD. 1/4 S 6 BT.

IN THE PRESENCE OF: DICK ANDERSON