

1. T. 6 S. R. 10W. No. L-17 Cor. $\frac{1}{4}$ Mer. Will. State ORG. N. F. SILVERLAW Dist. HeBo

2. Corner Status

3. Original Description Vol. Page Where Recorded

4. Description of Corners: #1000

5. Investigation Notes:

FOUND 4"x4" SQUARED TOP LIMB 24 IN. LONG IN DECAYED CONDITION LYING UPON THE GROUND.

FOUND 30 IN. HIGH ROTTED STUMP S. 49° W., 17 LKS. WITH ORIG. MARKS $\frac{1}{4}$ SBT.

FOUND ROTTED STUMP (ORIG) S. 69° E., 20 LKS. WITH ALL MARKS ROTTED OFF.

6. Signed L. WHITMORE Title FORESTRY TECH Date 9-27-63

7. Photo Identification
Photo No. _____
Ident. By: _____

8. Plane Coordinates Position Data
State _____ Zone _____
X _____
Y _____
Etab. By _____
Field Book No. _____
Where Filed _____

9. Evaluation
Authentic
Needs Verif. Monument
Re-estab. Survey _____
Land Status RRW - R.D.

Witness

EDWARD WHITMORE IS A DEPUTY COUNTY SURVEYOR
EMPOWERED TO RE-WITNESS POSITIVE EVIDENCE OF
ORIGINAL MONUMENTS. J. C. [Signature] 2/20/71

Field Book _____ Page _____

13. Recorded By _____ Volume _____ Page _____
(Agency) _____
(Date) _____ (City) _____ (County) _____ (State) _____

Remarks: THE PROPORTIONED $\frac{1}{4}$ CORNER SET BY THE USFS YEARS AGO IS N. 10° W. 10 FT. OF WHICH I DESTROYED. C. MOORE

SET A $\frac{3}{4}$ " PIPE 30 IN. ABOVE GROUND ALONGSIDE A 5"x5" SPRUCE LIMB 4 FT. ABOVE GROUND MKD. ~~S14~~ S14 ON E. AND S15 ON W. SIDES.

MARK BT^s IN THE PRESENCE OF
1 IN. SPRUCE, N. 17° W., 2 LKS. MKD. $\frac{1}{4}$ S15 BT. ED GORY
1 IN. HEMLOCK, N. 66° 30' E., 92 LKS. MKD. $\frac{1}{4}$ S14 BT. MORRIS STERLING