


USDA-FOREST SERVICE 6P R.D. Hebo County TILLA. - LINCOLN
 Index File No. N-13 N.F. SIUSLAH State ORE.

T 6 S R. 10 W
 Merid. Will.

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND GL 1880 SET POST 4 MKD,
7" SPRUCE, S. 4° W, 42 LKS.
12" SPRUCE, N. 88° W, 13 LKS.
14" Hem., N. 7° E, 34 LKS. #1003

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
FOUND GALV. PIPE 12" HIGH.
FOUND 52" SPRUCE, S. 1° W, 27 3/4 FT. WITH A CHOPPED OPEN FACE ROTTED.
FOUND 42" SPRUCE, N. 88° W, 8 1/2 FT. WITH HEALD.

PHOTO IDENTIFICATION DATA
 Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____

WITNESS FACE.
 DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
FOUND 36" Hem., N. 27° E, 22 1/4 FT. BLOWN DOWN AND ROTTED OPEN FACE.
ORIGINAL BLAZES CAN BE FOUND ON A LINE TO THE NORTH.

PLANE COORDINATE POSITION
 State _____ Zone _____
COPIES SENT TO NAIL LOCATION SIGNS ON BT.

Signature Leonard Whitmore Division Lumber Headquarters Hebo Date 4-30-73 7100-52 (13/60)

TITLE _____

DATE: _____

PHOTO# _____

IN THE PRESENCE OF: _____

COMMENTS:
No data this side

NEW ACCESSORY:
 " X " Hat Section " S. E. feet
 " Post N.W. feet

I SET

REWITNESS