

1. T. 6 S. R. 10 W. No. 5 N. Cor. SEC. Mer. 11 1/2 State Ill. (Rectangular) N. F. SIUSLAW Dist. HEBO

2. Corner Status

18	17
17	18

3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners:
POST **#1009**

5. Investigation Notes: part gone
 Found the original post lying upon the ground with visible scribbling S18.
 Found one original N.W. alder bearing tree stump with all scribbling rotted away and in its proper distance and bearing.

7. Photo Identification
 Photo No. _____
 Ident. By: _____

8. Plane Coordinate Position Data
 State _____ Zone _____
 X _____
 Y _____
 Estab. By _____
 Field Book No. _____
 Where Filed _____

9. Evaluation
 Authentic
 Needs Verif. Monument
 Re-estab. Survey _____
 and Status PRIV - N.E.

6. Signed T. J. ... Title ... Date 5-3-61

RE-ESTABLISHMENT RECORD

Set a corner line 3" diameter iron pipe and scribe S17 on N.E. face of post.

Accessories 8 ft

Mon. measured N 48° E, 55 ft. slope set. located T6 S. R. 10 W. S. 17 F. S. BT

Mon. measured N 47° 30' W, 67 ft. slope set. located T6 S. R. 10 W. S. 18 F. S. BT

By T. J. ... Title ... Agency ... Date ...

13. Recorded By ... (Agency) ... Volume ... Page ...
 (Date) ... (City) ... (County) ... (State) ...

Remarks:
 Set a second line post along Kingsbolt road 445 ft. east of old corner.
LEONARD WHITMORE IS A DEPUTY COUNTY SURVEYOR
EMPOWERED TO RE-WITNESS POSITIVE EVIDENCE OF ORIGINAL MONUMENTS.
...