CHAINS

Page 21.

TLSR9W

 $\frac{1}{4}$ corner for sections 10-15 Original Monument: Fir post Mkd. $\frac{1}{4}S10$ on N. and $\frac{1}{4}S15$ on S. sides

Original Witness: 40" snag, N.54°30'W.,374Lks.,Mkd. ½S10BT 6" Willow, S.15°30'W., 121Lks.,Mkd. ½S15BT

I found the original post lying upon the ground with visible marks "45". Found 8" willow, S.15°30'W., 80ft. lying upon the ground with all marks rotted away. Found 40" snag, N.54°30'W., 246/8 ft. with all marks rotted away. An old fence lying upon the ground cornered at this post and runs in a southerly direction. The original post was in such a solid condition I put it back into the ground and built a mound of rock on the east side.

I marked 2 new BTs:
14" fir, N.61°30'E., 11½ft. Mkd. ½S10BT.
12" fir, S.39°W., 12ft. Mkd. ½S15BT

Witness: L. Whitmore by M. Whitmore, Tillamook Co. deputy surveyor. 2-4-61

TLSR9W

14 13 Section corner to sections 13-14-23-24 Original Monument: Fir post.

Original Witnesses: 40 snag, N.54°E., 146Lks. Mkd. T4SR9WS13 BT 24" snag, S.77°E., 195Lks. Mkd. T4SR9WS24 BT 48" snag, S.67°30'W., 46½Lks. Mkd. T4SR9WS23BT 48" snag, N.36°30'W., 54½Lks. Mkd. T4SR9WS14BT

I found the original rock mound but the post had rotted away. Found 48" snag, S.67°30'W., 31ft. with visible scribe Mks. "BT". Found 48" snag, N.3630'W., 36ft. with visible but not legible scribe marks. The original NE and SE BTs are in their proper bearings and distances but all Mks. are rotted away. I set a squared post in rock mound and I marked 4 new BTs: 16" fir, S.62°W., 13ft. Mkd. T4SR9WS23BT

BOOK 3

ชบบห ร