CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

This corner was set by proportionate measurement by the General Land Office in 1933 under a dependant resurvey of T 4 S and R 8 W. They set a brasscap from which

30" Fir S 32° W 27 Links 8" Fir N 9° E 45 Links

DIAGRAM T 4 S R 8 W 1/4 3/2 Z

Description of corner evidence found:

We found the brasscap badly bent and out of position. We reset a 2 1/2" X 30" galvanized Iron pipe with brasscap and marked one bearing tree.

25" D. Fir N 09° E 29.7 feet 42" D. Fir Stump S 32° W 17.8 feet

Description of monument and accessories I established to perpetuate the original location of this corner:

I set a 2 1/2" X 30" galvanized iron pipe with a flared bottom and a brasscap riveted to the top marked.

T 4 S R 8 W From Which, 1/4 14" Douglas Fir S 19° W, 43.7 feet Scribed "1/4 S 3" "B.T." S 3 | S 2 25" Douglas Fir N 09° E, 29.7 feet 1977 42" Douglas Fir Stump S 32° W, 17.8 feet RLS 1073

I set two 6' steel fence posts with Boundary signs and Land Survey signs. All bearing trees have brass washers, attention signs, bearing tree tags, and red painted bands on them.

Witness: Mike Jackson

Sec. Map B. 764

D. Mike Jackson Engineering Technician Office of MINNY DARKEYS County of MANAGON

- I Consider of County Surveyor

(COUNTY OFFICIAL)

Form R6-7100-57 (9/71)

Book 6

HIMBERLAND SERVICES, INC. 1010 Airport Soas - P. O. Box 968 Albany - Oregon - 97321 Telephone - 7503 - 926-9404

LAND SURVEYING - ENGINEERING LAND USE PLANNING - ROADS FORESTRY CONSULTING

REGISTERED PROFESSIONAL and survey

KENNETH M. WIGHTMAN II

REGISTERED PROFESSIONAL

EDGAR R. COOK