## OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

SECTION: Southeast	TOWNSHIP 2 South	RAN	GF 10	) West
SECTION: Southeast corner of Section 4				
COUNTY: Tillamook	Control of the contro	udom p'et e	DATE: 10-28-08	
	ction corner common to Sections 3,	4, 9.	T	(Please check one)
and 10, Township 2 South, Range 10 West, W.M.				Condition Report Only
			l iii	Not Found
				Rewitness
				Unrecorded
ı				
				Surveyed In
			ļĢ	Referenced Out
Previous Rewitnesses, Restorations and Surveys, etc.: Rewitness card number 441; Rewitness Book 1, Page 96, Rewitness Book 4, Page 89, Rewitness Book 5, Page 72, Survey maps B-45, B-243, B-659, B-658, Tillamook County Survey Records.				
Found Monument(s) and Accessories (Condition & Source): Found a 3" diameter Tillamook County Brass cap in concrete and tile in good condition and stamped as shown hereon. I placed a 12" diameter plastic cylinder and 120 pounds of concrete around the found monument. Found a hat section post located North 1.5' and placed new yellow metal location tag on hat section post. Found a 4" x 4" white cedar post located North 1.5' and placed concrete around the base of the post. Found a 1-1/4" iron pipe lying next to the found monument.  Found a Spruce stump (80" in Rewitness Book 4, Page 89) with a yellow metal location tag at record position.  Found a badly rotten Hemlock stump (48" in Rewitness Book 4, Page 89) with a yellow metal location tags at record position.  Found a badly rotten Hemlock stump (30" in Rewitness Book 4, Page 89) at record position, with a 6" diameter Hemlock tree growing out of the top of rotten stump.				
Monument Set (Procedures a	and Description): Not Applicable.		Sket	ch of Found Monument:
; •				
				T 2 S R 10 W  4   3  9   10  RS 287 1977
New accessories set: No new accessories set.				
New Bearing Trees:  17" diameter Spruce tree scribed "T2SR10WS4BT" with a nail and aluminum washer stamped "TILL.CO.SURVEYOR' which bears North 58° West 31.0'.  22" diameter Douglas Fir tree scribed "T2SR10WS10BT" with a nail and aluminum washer stamped "TILL.CO.SURVEYOR' which bears South 55° East 56.1'.  15" diameter Twin Hemlock tree scribed "T2SR10WS9BT" with a nail and aluminum washer stamped "TILL.CO.SURVEYOR' which bears South 67° West 12.6'.  14" diameter Hemlock tree scribed "T2SR10WS3BT" with a nail and aluminum washer stamped "TILL.CO.SURVEYOR' which bears North 4° East 7.7'.				
Location & Comments: This of 150' East of the existing road #	corner monument is located approx #100.	imately		
Firm / Agency:			(	SURVEYOR'S SEAL
Address: TILLAMOOK COUN	TY SURVEYOR'S OFFICE			
201 Laurel Avenue		1		REGISTERED
Tillamook, Oregon	97141	]	1	PROFESSIONAL
Party Chief: Joe Jensen, Surv	rey Supervisor			LAND SURVEYOR
•				and V America
Notes:	aggeren i general de partir de la companya de la co			aseph V. Geusen OREGON JANUARY 10, 2008
Witness: Danny R. McNutt, Ti	llamook County Surveyor			JOSEPH V. JENSEN 60067 RENEWAL DATE: 08-30-09
March or transition to a second law or the March of the Article of the March of the Article of the March of t	<u> </u>	Ä		TENTENTE DATE OF OUT 1