OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

SECTION: SE Corner of Section 34	TOWNSHIP 2 South	RANC	ANGE 10 West	
COUNTY: Tillamook			DATE: 01-07-09	
CORNER DESIGNATION: The Southeast Section Corner of Section 34			the state of the s	
and the Southwest Section Corner of Section 35, T. 2 S., R. 10 W., W.M. Said corner is also on the North line of Section 3, T. 3 S., R. 10 W., W.M.				Condition Report Only
			1	Restoration
			図	Rewitness
			6	Unrecorded
			旨	Reset
			H	Referenced Out
Previous Rewitnesses, Restorations and Surveys, etc.: B.L.M Field Notes Volume: OR-R0053 Page: 0125 (G.				
2S10 Page 7, 1857), Book 3 Page 302, 1969, Book 6 Page 3, 1976, B-738, Tillamook County Survey Records.				
Found Monument(s) and Accessories (Condition & Source): Found 3" brass cap, flush, in good condition. The				
monument is stamped as shown hereon. Tied the monument using GPS. The Oregon North Zone State Plane in NAD				
83/91 coordinate for the monument is N = 631104.178, E = 7331656.286. Found remains of white post near the cap.				
(Book 3, Page 302) – Found 24" (was 14") dia. Hemlock Stump, 6' tall, scribing partially visible, bears (N 44° E 52.1').				
(Book 3, Page 302) - Found 17" (was 12") dia. Hemlock Stump, 4' tall, half burnt, scrib.part. visible, bears (N 43° W 14.8').				
(Book 3, Page 302) - Found 12" (was 10") dia. Spruce Stump, 4' tall, scribing partially visible, bears (S 46° W 14.3').				
() Indicates record from Book 3, Page 302, Tillamook County Survey Records.				
Monument Set (Procedures a	nd Description): Not Applicable.		Sketo	ch of Found Monument:
		Ī		
		l		1969
			12S 23	
				34 35
				3
		1	T3S	
		1	RS 376	
		l		
<u> </u>				
Other new accessories set: Set 120 lbs. of concrete in a 12" dia. cylinder around corner. Set a 72" hat section post 2.0'				
				Co. Survey", on the west edge of logging
				State Plane NAD 83/91 coordinate for
				a R.P.C. marked, "Tillamook Co. Survey", ent. The Oregon North Zone State Plane
	point is N = 631002.0410, E = 73316			ent. The Oregon North Zone State Flane
R.P.C. indicates "Red Plastic C		, 10, 100		
New Bearing Trees:				
No suitable trees in the area.				
		····		
	corner is located approximately 30' e		-	
	imately 100' south of Yellow Fir mai	nline	-	
logging road.		******		OHOVEVODIC CE AL
Firm / Agency Address: TILLAMOOK COUN	TV CLIDVEVODIC OFFICE			SURVEYOR'S SEAL
Address, TILLAMOOR COUN	11 SURVETUR S OFFICE			
Party Chief: Joe Jensen, PLS	60067 Survey Supervisor			REGISTERED
Party Cities. Joe Jensen, FLO	50007, Survey Supervisor	ļ	4	PROFESSIONAL
		1		LAND SURVEYOR
Notes:			1	CAGO COLLACION
				Agrosh V. Gensea
	ny niana-ny aora-an-an-an-an-an-an-an-an-an-an-an-an-an			
Witness: Danny R. McNutt, PLS 49230, Tillamook County Surveyor			OREGON JANUARY 10, 2008	
Michael R. Rice, LSI	16723, Survey Technician	1	į	JOSEPH V. JENSEN
To compare the second s			1	60067
				RENEWAL DATE: 06-30-09



 $G: \verb|\completed restorations| T2\&3SR10WSec34,35,3.doc$