OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT

	Tillamook County	Surveyor'	s Of	fice	
SECTION: 8	TOWNSHIP 2 South	RANG	E 10	10 West	
COUNTY: Tillamook				DATE: 4-15-09	
	e Section Corner common to Section	n 8 9 16		(Please check one)	
INCORNER DESIGNATION: THE	5 Dection Contention to Section	1, 0, 9, 10		Condition Report Only	
mu ir.				Restoration	
				Rewitness	
				Unrecorded	
				Reset at surface	
				Referenced Out	
17-18) (1857), Book 1 Page 93 (1446 (1978), Map B-983 (1981) Found Monument(s) and Accipound hat section post with a year ost lying down on the east side conventionally using GPS estate monument is N = 652873.0 (G.L.O.) – Did not find the (30" (G.L.O.) – Did not find the (18" (G.L.O.) – Found 96" (was 30") (Book 1, Page 93) – Did not find Book 1, Page 93) – Did not find Rewitness #446) – Found 53" (grown into face.	(1950) same as Book 4 Page 84 (1), Map A-4571 (1981), Map P-113 (1985), Map P-113 (1986), Map P-113 (1	950), Map 1987), Tilla ound a 2 1 uth 1.5' fro is stamped one State g (N 64° 10 96.8'). I 13° W 94 () 94.3' (95	A-14 imoc /2" b m th d as Plan 09 lk	prass cap in broken tile and cement, up 0.7' e monument. Found a 4" X 4" white cedar shown hereon. Tied the monument le in NAD 83/91 grid coordinate position for	
) Indicates record information	n from Tillamook County Survey Re	cords.			
	nd Description): Not applicable.		of F	ound Monument:	
				8 9 17 16	
with a red plastic cap stamped, North Zone State Plane in NAD Feet. Set a 5/8" X 30" Iron Roo to tie the brass cap. The Orego N =652760.781, E = 7322133.2 marked, Till. Co. Surveyor" bet	, "Tillamook Co. Survey" in the clear D 83/91 grid coordinate position for t d with a red plastic cap stamped, "T on North Zone State Plane in NAD 8 262, U.S. Feet. We then scribed the	-cut, as ar the Iron Ro illamook C 3/91 grid o	occ dis o. Si	nd monument. Set a 5/8" X 30" Iron Rod supy point to tie the brass cap. The Oregon N = 652830.798, E = 7322034.187, U.S. urvey" in the clear-cut, as a backsight point finate position for the Iron Rod is "Spruce, "BT" and set a nail and washer	
*60" Spruce bears S 23° E 94. * Indicates yellow metal locatio All new bearing trees have a na	.1', scribed, "T2S R10W S9 BT", tag 7', scribed, "T2S R10W S16 BT", ta in tag affixed to new bearing tree. ail and aluminum washer marked, " her is located at the toe of a ridge, no	gged and Till. Co. Su	paint	ed. ted. or", in between the scribed B and T.	
East/West running timber line,		· · · · · · · · · · · · · · · · · · ·		SURVEYOR'S SEAL AMOOR	
<i>Firm / Agency Addr</i> ess: TILLAMOOK COUN	ITY SURVEYOR'S OFFICE			JOHN DO SEAL TO SEAL T	
201 Laurel Avenue Tillamook, Oregon				REGISTERED MAY 1	
Party Chief: Joe Jensen, P.L.S. 60067, Survey Supervisor				LAND SURVEYOR	
Notes:			Ì	Jaseph 1 Gensen	
Witnesses: Danny R. McNutt,	P.L.S. 49230, Tillamook County Su S.I. 16723, Survey Technician	ırveyor.		OREGON JANIJARY 10, 2006	

G:\completed restorations\T2SR10WSec8,9,16,17.doc

492 BOOK

OREGON
JANUARY 10, 2006
JOSEPH V. JENSEN

60067 RENEWAL DATE: 08-30-09