## OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

SECTION: 36	TOWNSHIP 3 South	RANGE 10 West	
COUNTY: Tillamook		No.	DATE: 5-08-09
CORNER DESIGNATION: The Quarter Corner common to Sections 3		35	(Please check one)
and 36, T. 3 S., R. 10 W., W.M.			Condition Report Only
			Restoration
		<b>E</b>	Rewitness
			Unrecorded
			Reset at surface
Provious Rewitnesses Restorations and Surveys at a DI M Sield Not			Referenced Out
Previous Rewitnesses, Restorations and Surveys, etc: BLM Field Notes Volume: OR-R0272 Page 111, (GLO 3S10 Pg. 7) (1882), Map B-505 (1965), Map B-1046 (1982), Tillamook County Survey Records.			
Found Monument(s) and Accessories (Condition & Source): Found a 3" O.S.B.F. Brass Cap protruding 0.6', leaning slightly, plumbed and rotated cap North. The monument is stamped as shown hereon. Tied the monument conventionally using GPS established control. The Oregon North Zone State Plane in NAD 83/91 grid coordinate position for the monument is N = 601300.089, E = 7336163.784, U.S. Feet. Found a carsonite post South 6.0' of the monument.  (G.L.O.) – Did not find the (6" dia. Vine Maple for corner, marked on W face "1/4 S").  (G.L.O.) – Did not find the (8" diameter Vine Maple bearing N 6° W 5 lks.).  (G.L.O.) – Did not find the (6" diameter Vine Maple bearing S 2° W 18 lks.).  (Map B-505) – Found rotten Hemlock Stump (was 35" dia.), 5' tall, bearing (N 67 3/4° W 58.2'), with rusty metal location tag.  (Map B-505) – Found rotten Hemlock Stump (was 34" dia.), 5' tall, bearing S 11° E 17.7' (S 14 1/2° E 16.4'), hill is eroding, causing stump to lean and slide.  (Map B-505) – Found 1" dia. Iron Pipe, leaning and disturbed, Northeasterly 8.1' (N 35°27' E 9.35').			
( ) Indicates record information from Tillamook County Survey Records.  Monument Set (Procedures and Description): Not applicable.  Sketch of Found Monument:			
from monument. Set 72" hat sect	ion post with a yellow metal location	nder around monument. Reset carsonite post easterly 2.5' ation poster North 3.0' from monument. Set a 5/8" X 30" iron	
rod with a red plastic cap marked, "Tillamook Co. Survey", for occupy point to conventionally tie the monument. The Oregon North Zone State Plane grid coordinate in NAD 83/91 is N = 601402.764, E = 7336208.443, US Feet. Set a 5/8" X 30" iron rod with a red plastic cap marked, "Tillamook Co. Survey", as a backsight point to conventionally tie the monument. The Oregon North Zone State Plane in NAD 83/91 grid coordinate for said point is N = 601391.220, E = 7336319.251, US Feet.			
New Bearing Trees set:  14" dia. Fir bearing N 40° W 24.2', scribed, "T3S R10W 1/4 S35 BT", tagged and painted.  18" dia. Hemlock bearing N 17°30' E 21.6', scribed, "1/4 S36 BT", tagged and painted.  12" dia. Fir bearing S 29° W 7.1', scribed, "1/4 S35 BT", tagged and painted.  All new bearing trees have an aluminum nail and washer marked, "Till. Co. Surveyor" on the face between the scribed "B" and "T". All new bearing trees also have a yellow metal location tag affixed.  Location & Comments: This corner is located approximately 75' east of an existing logging road.			
existing logging road.  Firm / Agency	The state of the s		SURVEYOR'S SEAL
Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue			SURVETUR S SEAL
Tillamook, Oregon 97141  Party Chief: Joe Jensen, P.L.S. 60067, Survey Supervisor			REGISTERED PROFESSIONAL LAND SURVEYOR
Notes:			Grase M. V. Varia
	L.S. 49230, Tillamook County Surve II. 16723, Survey Technician	yor.	OREGON JANUARY 10, 2008 JOSEPH V. JENSEN 60067
		图	RENEWAL DATE: 08-30- Z011

 $G: \verb|\completed| restorations \verb|\T3SR10WQuart35-36.doc| \\$ 

BOOK 7 515