OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

SECTION: 35	TOWNSHIP 2 South	RANGE	RANGE 9 West	
COUNTY: Tillamook			DATE: 6-21-09	
CORNER DESIGNATION: The Quarter Corner common to Section 35 and		and	(Please check one)	
Section 36.		Ĩ		Condition Report Only
				Restoration
			Ø	Rewitness
				Unrecorded
		Ī		Reset at surface
		1		Referenced Out
Previous Rewitnesses, Restorations and Surveys, etc: BLM Field Notes Vo			me	: OR-R0309 Page 963 (GLO 2S9 Page 50)
(1884), Rewitness Book 1 Page 236 (1955), BLM Field Notes Volume: OR-R0567 Page 95 (1956), Rewitness Book 7 Page 375 (2004), Tillamook County Survey Records.				
Found Monument(s) and Accessories (Condition & Source): Found a 2 1/2" G.L.O. Brass Cap leaning badly with concrete and rock collar disturbed, in a recently logged area, on a steep hillside. The monument was set in BLM Field Notes Volume: OR-R0567 Page 95 (1956). The monument is stamped as shown hereon. We used the only remaining accessories, as best physical evidence, to straighten the monument. We then tied the monument directly using GPS established control. The Oregon North Zone State Plane in NAD 83/91 grid coordinate for the monument is N = 631820.777, E = 7368628.229, US Survey Feet. (G.L.O.) – Did not find the (Hemlock 16" diam. bears S 81° E 12 lks. [7.92']). (G.L.O.) – Did not find the (Hemlock 9" diam. bears N 51°30' W 24 lks. [15.84']). (Book 1, Page 236) – Did not find the (26" Hemlock bears S 30° W 23 feet slope distance). (Book 1, Page 236) – Found 20" dia. rotted Hemlock Stub (was 18"), 6' tall, bears (S 45° E 34.5' slope distance) scribe partially visible. (BLM Field Notes) – Did not find the (Hemlock 10 ins. diam., bears S 19 1/4° E 58 lks. [38.28']). (BLM Field Notes) – Did not find the (Hemlock 10 ins. diam., bears N 70° W 71lks. [46.86']). (Book 7, Page 375) – Found Hemlock uproot, out of position, (was 15" Hemlock N 12° E 19.39 feet). (Book 7, Page 375) – Found 17" Hemlock Stub, 7' tall, bears (N 86° E 20.66 feet) scribing visible, yellow metal location tag, used nail and washer to position the corner. (Book 7, Page 375) – Found (72" light hat section post) lying down.				
[] Indicates converted value from Monument Set (Procedures and		Skotah c	f E	ound Monument:
			1/4 1/4 1/4 1/4 1/50 FOR PEND TO THE TOTAL	
New accessories set: Reset rock collar and 120 lbs. of concrete in an irregular mass. Reset found hat section post North 3.0' from monument.				
New Bearing Trees set: 30" dia. Cedar bears S 68° E 77.2', scribed "1/4 S36 BT", with a yellow metal location tag and an aluminum nail with washer marked "Till. Co. Surveyor" nailed to the face. Location & Comments: Corner is located approx. 50' westerly of a gravel				
logging road, on a steep slope, in a		3761		100 to the state of the state o
Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tillamook, Oregon 97141				REGISTERED PROFESSIONAL
Party Chief: Joe Jensen, P.L.S. 60067, Survey Supervisor				LAND SURVEYOR
Notes: Digital images were ta trees, and the new bearing tree.	nages were taken of the monument, the found bearing paring tree.			Jaseph V. Gensen OREGON
	.L.S. 49230, Tillamook County Surveyor S.I. 16723, Survey Technician			JANUARY 10, 2008 JOSEPH V. JENSEN 60067 RENEWAL DATE: 06-30- 2011
		OOK CO		

G:\completed restorations\T2SR9WQuarterSec35Sec36.doc