OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

SECTION: East 1/4 corner Section 12	TOWNSHIP 3 South	RANGE 8 West			
COUNTY: Tillamook			·····	DATE: 03-05-10	
CORNER DESIGNATION: The Quarter Corner Common to Section 7, T. 3				(Please check one)	
S., R. 7 W. and Section 12, T. 3 S., R. 8 W., W.M.				Condition Report Only	
, , , , , , , , , , , , , , , , , , ,	,	ļ		Restoration	
		-	<u> </u>	Rewitness	
			=	Unrecorded	
l l				Reset at surface	
				Referenced Out	
Previous Rewitnesses, Restorations and Surveys, etc: BLM Field Notes Volume: OR-R0569 Page 0388.00 to 0389.00,					
1960; Survey map number A-859, Tillamook County Survey Records. Found Monument(s) and Accessories (Condition & Source): Found a 3" Bureau of Land Management brass cap					
approximately 1.0' above the ground and in good condition. The monument is stamped as shown hereon. Placed a 12" diameter plastic cylinder filled with 120 pounds of concrete around the monument. GPS tied the monument directly using GPS established control. The GPS control point is BLAI (BLAINE) established by the Tillamook County HARN (High Accuracy Reference Network). This was a single-occupation observation only. The Oregon North Zone State Plane in NAD 83/91 coordinate for the monument is N = 619441.746, E = 7403190.560, U.S. Survey Foot, Convergence = -2° 12' 12.18168, Grid Scale = 0.99989823. Found an aluminum pipe without a cap and we GPS tied the pipe. The pipe bears North 49° 37' 32" West 34.09' and are grid values. (BLM Field Notes Volume: OR-R0569 Page 0388.00) – Found the 50" diameter Fir stump bearing N 74° E 45 lks. [29.7'], no scribing visible, stump is located at record position. (BLM Field Notes Volume: OR-R0569 Page 0389.00) – Found the 42" diameter Fir stump bearing N 83° W 291/2 lks. [19.47'], with scribing visible, stump is located at record position. () Indicates record information from BLM					
[] Indicates conversion from links		Ckatab	-4 E	ound Monument:	
Monument Set (Procedures and	Description). Not applicable.	Sketch	JI F	CADA STRAL	
		S12 S7 S12 S7 R8W R7W 1959 LAND MANACHER CLAND MANACHER			
New accessories set: Set a 72" hat section post 3.0' North of monument.					
New Bearing Trees set: No new bearing trees set.					
Location & Comments: The corner is located at the end of a spur road approx. 50' East of the end of the road.					
Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tillamook, Oregon 97141				SURVEYOR'S SEAL REGISTERED	
Party Chief: Joe Jensen, P.L.S. 60067, Survey Supervisor			r L	PROFESSIONAL LAND SURVEYOR	
Notes: Digital images were taken of the found monument, the new monument, the record bearing trees and new accessories.				OREGON JANUARY OR	
Witnesses: Danny R. McNutt, P.L.S. 49230, Tillamook County Surveyor Michael R. Rice, L.S.I. 16723, Survey Technician				JANUARY 10, 2008 JOSEPH V. JENSEN 60067 RENEWAL DATE: 08-30- 2011	

