## OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

SECTION: East % of Section 22 TOWNSHIP 2 North RANGE 10 West				
COUNTY: Tillamook			DATE: 6-1-10	
CORNER DESIGNATION: The Quarter Corner Common to Sections 22 ar			(Piease check one)	
23 T. 2 N., R. 10 W., W.M.			]	Condition Report Only
			]	Restoration
		Ē		
		T	<b>5</b>	Unrecorded
			3	Reset at surface
				Referenced Out
Previous Rewitnesses, Restorations and Surveys, etc: BLM Field Notes Volume: OR-R0122 Page 123, 1873; Tillamook County GLO Book 2N10, Pg. 25, 1873; Rewitness Book 2, Page 270 ,1953; Map B-844, 1979; Tillamook County Survey Records.				
Found Monument(s) and Accessories (Condition & Source): Searched for and did not find the iron pipe, a center-punched car axle as described on map B-844, which was set by W.A. Markham and described in Rewitness Book 2, Page 270, Tillamook County Survey Records. This area is in a recent clear cut and the monument could not be found.				
(G.L.O.) – Found a 15' tall partially rotted Hemlock snag with no visible scribing. A rusty yellow metal location poster tag was found at the base of this snag (was a 5" diameter Hemlock tree at S 58° W 14 links = 9.24') at record position.				
(Book 2, Page 270) – Found a 21" X 28" X 1' tall irregular shaped Hemlock stump with a chopped out triangle at record position; was a 14" diameter Hemlock tree at N 28° E 15.0 feet. Nailed a new yellow metal location poster tag scribed with the record bearing tree information from Rewitness Book 2, Page 270 to the stump.  ( ) Indicates record GLO information.  ( ) 1 Indicates record information Map B-844, Tillamook County Survey Records.				
Monument Set (Procedures and Description): Sketch of Set Monument:				
Monument Set (Procedures and Description): We established GPS control points near the corner location. GPS observations were taken on a nail and washer in 2 10" diameter Hemlock tree stumps. These stumps were used as control to set the corner monument. GPS coordinates in NAD 83-91, State Plane Coordinates Oregon North Zone U.S. Survey Foot, were obtained for the set corner monument, Coordinate at instrument setup is		oneigh Of	- <b>5</b> (	T2N R10W
Northing = 738240.99, Easting = 7336356.85. Coordinate at the backsight point is Northing = 738248.97, Easting = 7336294.11.				2010
Set a 36" x 2-1/2" iron pipe and a 3" diameter Tillamook County Survey Brass Cap in a 12" diameter plastic cylinder and 120 pounds of concrete. The brass cap is stamped as shown hereon.				
GPS coordinates in NAD 83-91, State Plane Coordinates Oregon North Zone U.S. Survey Foot, were obtained for the set corner monument, Northing = 738232.355, Easting = 7336339.077. and on the nails set as references to the corner monument.				
New accessories set: Set a 72" hat section post with a yellow metal location tag 3.0' East of the monument. Grid bearing and				
distance from nail and washer at instrument setup to corner monument = \$ 64° 05' 14" W 19.76 feet. Grid bearing and distance				
from nail and washer at backsight setup to corner monument = \$ 69° 43' 16" E 47.94 feet.				
New Bearing Trees set: No new bearing trees were set.				
			Rose	
Location & Comments: Corner is located approximately 300' North of Vermilyea Road.				
Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE			-	SURVEYOR'S SEAL
201 Laurel Avenue				DECIGHTEDED
Tillamook, Oregon 97141				REGISTERED PROFESSIONAL
	Party Chief: Joe Jensen, P.L.S. 60067, Survey Supervisor			LAND SURVEYOR
<b>Notes:</b> Digital images were taken of the found monument, the record bearing trees and new accessories.				Gaseph V. Geusen OREGON JANUARY 10, 2008
Witnesses: Danny R. McNutt, P.L.S. 49230, Tillamook County Surveyor Michael R. Rice, L.S.I. 16723, Survey Technician  JOSEPH V. JENSEN 60067  RENEWAL DATE: 08-30-20 []				

G:\completed restorations\T2NR10WQuarterE22-W23.doc