OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

SECTION: 35 and 2	TOWNSHIPS 1 North and 1 South	RANG	RANGES 10 West	
COUNTY: Tillamook		DATE: 06-22-11		
CORNER DESIGNATION: The One-quarter Corner common to Section			T	(Please check one)
35, T1N R10W and , Section 2,		·= - •		Condition Report Only
,				Restoration
			Œ	Rewitness
			Unrecorded	
			Reset	
				Referenced Out
Previous Rewitnesses, Restorations and Surveys, etc.; BLM Field Note Volume: OR-R0053, Page 26 (1856); Tillamook County GLO Book T1S R10W, Page 2; Tillamook County GLO Book T1N R10W, Page 21; Tillamook County Rewitness Card #59 (1970); Rewitness Book 6, Page 499; Tillamook County Survey Records. See previous rewitness cards for a more detailed history.				
Found Monument(s) and Accessories (Condition & Source): Found a 3" diameter Tillamook County brass cap in a 10" diameter cast iron monument case in concrete. This monument was left at position as an underground monument. The monument was found to be in good condition. I then placed a 2" diameter Tillamook County Brass Cap in 60 pounds of concrete at road surface. The 2" diameter brass cap is stamped as shown hereon. Found a 60" diameter Spruce tree with face overgrown and with white and yellow bearing tree tags (was a 50" Spruce tree with face overgrown bearing S.31° E 59.88', see Rewitness Book 6, Page 499). Found a 48" diameter x 5' tall Spruce stump with face overgrown (was 44" Spruce tree with face overgrown bearing S.72° E 98.26', see Rewitness Book 6, Page 499). Added a yellow metal location poster. Found a 43" diameter Spruce tree with face overgrown and with a grown-in white bearing tree tag (was a 38" Spruce tree with face overgrown bearing S.14° E 128.55', see Rewitness Book 6, Page 499). Added a yellow metal location poster.				
Monument Set (Procedures and Description): We referenced the existing location of the found monument in the 10" diameter cast iron monument box with rock nails set in the asphalt. We then filled the caliron monument box with concrete and placed the 2" diameter brass of and 6" x 3/4" iron pipe in the concrete at the referenced position.		on cast	Sketch of Set 2" Diameter Brass Cap at Road Surface: TIN RIOW S35 S2 TIS RIOW 2011	
Other new accessories set: We replaced the damaged 96" hat section post with a new hat section post and yellow metal location tag at the record position of North 24.15', the record value from Rewitness Book 6, Page 499. New Bearing Trees: No new bearing trees set.				
Location & Comments: This Bewleys Avenue and Baseline	comer is located at the intersection of Road in Bay City.	of		
Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tillamook, Oregon 97141 Party Chief: Joe Jensen, PLS 60067, Survey Supervisor and Deputy County Surveyor. Notes: Digital images were taken of the new monument and accessories. SURVEYOR REGISTER PROFESSI LAND SURV OREGON JANUARY 10 DOSEPH V		REGISTERED PROFESSIONAL		
		uty		Jaseph V. Jewsen
		+345************************************		OREGON JANUARY 10, 2008 JOSEPH V. JENSEN
Witness: Danny R. McNutt, PLS 49230, Tillamook County Surveyor Michael R. Rice, LSI 16723, Survey Technician			ļ	GOO67 RENEWAL DATE: 08-30-2013
	MOOK CO	>		

