OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

SECTION: SE of 16	TOWNSHIP 1 South	RANG	RANGE 10 West	
COUNTY: Tillamook	1	DATE: 7-24-12		
CORNER DESIGNATION: The Section Corner common to Sections 15, 16, (Please check one)				
21 and 22, T. 1 S., R. 10 W., W.M.		, .o,	12	Condition Report Only
				Restoration
			Н	Rewitness
			1	the state of the s
			무	Unrecorded
				Reset at surface
		لييسب		Referenced Out
Previous Rewitnesses, Restorations and Surveys, etc: BLM Field Notes Volume: OR-R0053 Page 198 (GLO Book 1S10 Page 33) (1857), Rewitness Book 10 Page 71 (1889), Map A-446 (1950), Map A-876 (1958), Map A-959 (1961), Rewitness Card #303 (1976), Map B-3505 (2012), Tillamook County Survey Records.				
Found Monument(s) and Accessories (Condition & Source): In 1976, a Rewitness was performed by Tillamook County Surveyor's Office, where they found some remaining GLO accessories and a 3/4" Iron Pipe with new Bearing Trees apparently set by CZ Corporation with no recorded evidence. They then set a new monument at the position of the found pipe.				
Now: Found 3" dia. Tillamook County Brass Cap, flush, in concrete, good condition. Found a 4" X 4" white cedar post (West 1.5'), hat section post (South 1.5'), 2" Iron Pipe leaning East (East 0.75'). Tied the monument using GPS directly. The Oregon North Zone NAD 83/91 grid coordinate in U.S. Survey Feet is: N= 678786.048, E= 7328540.875; Latitude: N 45°28'40.82095" Longitude: W 123°54'23.87469"				
The monument is stamped as shown hereon.				
(BLM) – Found rotten Hemlock Stump, was (20"), bears (N 85° W 22 lks. [14.52']), no visible marks. (BLM) – Did not find the 40" Hemlock bearing (S 36° W 61 lks. [40.26']). (BLM) – Did not find the 24" Hemlock bearing (S 50° E 76 lks. [50.16']). (BLM) – Found rotten snag, 8' tall, was (35" Hemlock bearing N 63° E 84 lks. [55.44']). (CZ Corp.) – Found rotten Hemlock Stump, 3' tall, was (48" Hemlock Stump), bears (N 18° E 37.48'), no visible marks. (CZ Corp.) – Did not find the (30" Hemlock Stump bears S 59° E 32.0'). (CZ Corp.) – Did not find the (36" Hemlock Stump bears S 30° E 48.77'). (Map B-3505) – Found 5/8" Iron Rod w/ Y.P.C. marked, "Terry Jones LS 2507" bearing (N 37°18'43" W 463.13'). (Map B-3505) – Found 5/8" Iron Rod w/ Y.P.C. marked, "Terry Jones LS 2507" bearing (S 00°06'22" W 292.53'). () Indicates record information, Tillamook County Survey Records. [] Indicates record links converted to feet.				
Monument Set (Procedures and	Description):	Sketch	of F	ound Monument:
			\	S16 S15 S21 S22 RS 287 1976 O DISTURB \$600 FIRE OR JETS
New Accessories set: N/A				
New Bearing Trees Marked:				
No suitable Bearing Trees. Location & Comments: Monume approx. 150' from the top and appr	ent is located on the west side of a rid ox. 200' South of the North End of a			
Road.			_	
Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tillamook, Oregon 97141				REGISTERED
Party Chief: Joe Jensen, P.L.S. 60067, Deputy County Surveyor				PROFESSIONAL AND SUPPLEYOR
Notes: Digital images were taken of the monument and its accessories.			1	LAND SURVEYOR
Witnesses: Danny R. McNutt, P.L.S. 49230, Tillamook County Surveyor				Goral V. Chenser
Michael R. Rice, P.L.S. 86926, Survey Technician				OREGON
JANUARY 10, 2008 JOSEPH V. JENSEN 60067 RENEWAL DATE: 08-30-2013				