## OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

| SECTION: Meander Corner of   | TOWNSHIP 1 South  | RANGE 10 West   |  |  |  |
|--|---|---|--|--|--|
| Section 15 and 16 COUNTY: Tillamook  |   | DATE: 3-15-13   |  |  |  |
|  | eander Corner common to Sections  | 15 and  |  | (Please check one)   |  |
| CORNER DESIGNATION: The Mi<br>16, T. 1 S., R. 10 W., W.M.  | carrier Corner community Sections   | , o estu  | X  | Condition Report Only  |  |
| 10, 1. 1 3., 13. 10 99., 99.191.   |   |   |  | Restoration  |  |
|  |   |   | 片  | Rewitness  |  |
|  |   |   | 片  | Unrecorded   |  |
|  |   |   | H  | Reset at surface   |  |
|  |   |   | 片  | Referenced Out   |  |
|  |   | lotos Vo  |  | e: OR-R0053 Page 200 (GLO 1S10, page 33  |  |
| 1857), Rewitness AMA Book 16, P<br>Page 99 (1962), Rewitness Book 4<br>Rewitness Card #285 (1969), Map<br>Found Monument(s) and Access<br>resurvey in Section 16, T. 1 S., R.<br>Iron Pipe. In 1958, a survey was p<br>line obtained from G. Collard (C.Z. | age 22 (1911), Map A-446 (1950), N<br>I, Page 101 (1962), Rewitness Book<br>A-3369 (1977), Tillamook County St<br>Fories (Condition & Source): Origin<br>10 W., was performed by W.E. Ande<br>erformed by John L. Carlich in said S<br>) R.S. #376. Said Iron Pipe was then | lap A-87 5, Page urvey Re nal Corn rson on Section 1 re-mon | 6 (1)<br>133<br>ecord<br>er w<br>Map<br>6. H<br>ume  | (1962), Map A-958 (1961), Rewitness Book 4, (1962), Rewitness Book 5, Page 202 (1966), is.  as set by GLO in 1857. In 1950, a dependent A-446 where he found an unrecorded 1 1/2" e noted the same Iron Pipe as being on a nted by the Tillamook County Surveyor's   |  |
| Found 3" dia Tillamook County Br   | #285 as the historical position and is  | Hat Sec   | tion   | Post destroyed lying next to the monument.   |  |
| The monument was then tied converged here in WGS 84, Latitude  | rentionally using GPS established co  | ntrol. Th   | e co   | ordinates have been converted and are  |  |
| North = 45°29'03.58622", West= 123°54'24.71570"  |   |   |  |  |  |
| (Book 4, Page 99) – Did not find the (Rewitness Card #285) – Did not le (Rewitness Card #285) – Did not le   | ne (14" dia. Alder bearing S 76° W 9.<br>ne (8" dia. Spruce bearing S 21°15' E<br>ook for (5/8" IR punched North 25.27<br>ook for (5/8" IR punched East 33.35'  | : 11.65')<br>" in CL o                                      | of Ba  | y Ocean Road).<br>Ocean Road).   |  |
| ( ) Indicates record information, 7  |   |   |  |  |  |
| N/A  |   |   | SI6 SI5  RS 287 1969  SION DISTURB SSOO FINE OR JUST AND DISTURB S |  |  |
|  | yellow metal location tag N 60° W 2.<br>angulation Station monument "Bould  |   |  |  |  |
| New Bearing Trees Marked:<br>N/A   |   |   |  | West of the second seco |  |
| Location & Comments:   | South of the CL of Bayocean Road in   | n the   |  |  |  |
| Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 1510 3 <sup>rd</sup> Street, Suite C Tillamook, Oregon 97141   |   |   |  | SURVEYOR'S SEAL  |  |
|  | L.S. 49230, Tillamook County Surve  | yor   |  | REGISTERED   |  |
| Notes: Digital images were taken of the monument and its accessories.  |   |   |  | PROFESSIONAL   |  |
|  |   |   | _  |  |  |
| Witnesses: Michael R. Rice, P.L.S. 86926, Survey Technician  |   |   | ŀ  | LAND SURVEYOR  |  |
| Piook colin  |   |   | لدجا   | OREGON<br>JULY 11, 2000  |  |
| िला १९ थाओं  |   |   |  | DANNY FI. MCNUTT   |  |

RENEWAL12 - 31- 2014-