## OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

SECTION: North 1/16 <sup>th</sup> corner of Section 18	TOWNSHIP 2 South	RANGE 9 West	
COUNTY: Tillamook			DATE: 05-11-15
Corner Designation:			(Please check one)
The North 1/16 <sup>th</sup> corner of Section 13, Township 2 South, Ra West & Section 18, Township 2 South, Range 9 West; W.M. Tillamook County, Oregon.		10 🗷	Condition Report Only
			Restoration
		10	Rewitness
		6	Unrecorded
			Brass Cap set at surface
			Referenced Out
Previous Rewitnesses, R Records.	estorations and Surveys, etc.: See	Map B-70	00, A-8393, Tillamook County Survey
Monument Set (Procedur			n of Found Monument:
			S13 \$ S18 S13 \$ S18
monument. A direct GPS of o field-tie the corner monument. New Bearing Trees set: N	ne. The purpose of this condition reports between the could not be obtained on the ment using a TOPCON total station. To new bearing trees were marked.  This corner is located approximately 10 groad on the top of a cut bank.	nis corner	tablish GPS coordinates on the corner. GPS control points were established
201 Laurel Aven Tillamook, Orego	on 97141	SI	JRVEYOR'S SEAL
Party Chief: Joe Jensen, Pand Deputy County Surveyo	PLS 60067, Survey Supervisor or.	Lü	NO SURVEYOR

G:\completed restorations\North One-SixteenthcornerSections13&18T2SR9W.doc

Notes: NAD83: N=650297.567,E=7343147.336, U.S. Survey Foot; WGS84; Latitude=45°24′05.79956″, Longitude=123°50′42.49695″; Convergence= -2°22′23.20326″; Grid Scale Factor=0.99990285 Witnesses: Danny R. McNutt, PLS 49230, Tillamook County Surveyor; Michael R. Rice, PLS 86926, Survey

Technician.

