26	25
35	36

TILLAMOOK COUNTY REWITNESS #412

SEC. COR. SEC. 26|25 / 35|36 T 2 S R 9 W., WM.

HISTORICAL: G.L.O. Pg. 50 259 1884

MICROFILM FICHE	MAPS	
5 OF 6 259	B-449	
	B-758	
	A-875	

CONDITION GOOD FOUND 1½" I.P. WITH 2½" B.C. G.L.O. MICROFILM FICHE 5 OF 6 259

FD. UPROOT STUMP	40" HEMLOCK	S. 10° E. 26 LKS	G.L.O. Pg. 50
NOT FOUND	4" HEMLOCK	S. 16 W. 43 LKS	G.L.O. Pg. 50
FD 30" HEM SNAG SCRIBING VISIBLE 27 ± TO FACE	30" HEMLOCK	N. 33°-15' W 43 LKS	G.L.O. Pg. 50
FD. 60" STUMP N. 70° E.	48" SPRUCE	N. 66° E 87 LKS	G.L.O. Pg. 50
NOW 12" ROTTEN STUMP 6' HIGH SCRIBING VISIBLE	8" HEMLOCK	N. 45° E. 48 LKS	MICROFILM 5 OF 6
FD 21" HEM. FACE GROWN OVER	10" HEMLOCK	S. 65° E. 188 LKS	MICROFILM 5 OF 6
NOW 17" ROTTEN STUMP 5' HIGH SCRIBING VISIBLE 16½' TO FACE	10" HEMLOCK	S. 83° W. 27 LKS	MICROFILM 5 OF 6
NOW 22" 16' HIGH STUMP ROTTEN 45± TO FACE SCRIBING VISIBLE	12" SPRUCE	N 35° W. 69 LKS	MICROFILM 5 OF 6

REWITNESS

I SET CONCRETE CYLINDER AROUND FOUND 1½" IRON PIPE WITH 2½" CAP WAS SET UPSIDE DOWN G.L.O. BRASS CAP. MICROFILM FICHE 5 OF 6 259

*60" Hat Section NORTH 19 FEET

1956
535/536
526/525
T25R9W
GENERAL LAND OFFICE

NEW ACCESSORY: DISTANCES ARE TO NAIL WITH WASHER IN FACE

*26" HEMLOCK GROWING ON 6' ⊗ CEDAR STUMP	N. 70° W. 51.14'	T2SR9W S26 BTCS
*9" HEMLOCK	N. 44° E. 46.43'	S. 25 BTCS
*21" HEMLOCK	S. 70° E. 68.67'	T2SR9W S36 BTCS
*9" ALDER	S. 41° W 49.20'	S35 BTCS

COMMENTS: THIS CORNER IS LOCATED ± 50' N. 40° E FROM AN OLD GROWN OVER LOGGING ROAD AND ± 34' SOUTH OF A SMALL CREEK & @ THE SOUTH EDGE OF AN OLD CAT ROAD. PIPE WAS FOUND LEANING BUT APPEARED TO BE SET IN THAT POSTURE.

IN THE PRESENCE OF: DAN McNUTT AL DVORAK

DATE: 3-5-85 PHOTO#: TITLE

*= County corner tag affixed.