Form 874-9—Revised May, 1918

U. S. Department of Agriculture

FOREST SERVICE

Siuslaw NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 4S R. 9W Willamette Mer.

1/4 Corner Corner common to Sections

, , 9, and 16

Corner consists of a Fir Limb (not) in place

State condition

Dimensions above ground 2 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION				DIAGONAL POSITION			
N	W	S	E	NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4 S	1/4 S		Found 9 [illegible]
BT	B		

Species	Alder	D.F.	2 [illegible]
Diameter	8"	30"	P.E.
Bearing	S22E	N35E	Now 38"
Distance	55'	16'	

Do you believe this to be a genuine Land Office Corner? (Yes)

If not, why? This was run in by A.A. Wilcox several years ago. Is probably in correct location.

[signature]
(Signature)

12/2/35 [illegible] Junior Forester
(Date) (Title)

8—7394

T. 4S R. 9W 1/4 cor. 9 and 16

Metal Location Poster is on a Post tree inches diameter, on the South side of Road from Hebo to Mt. Hebo from which this Corner bears South 450 feet chains distant.

Give any further facts which will aid in finding this Corner again.

This corner will be covered by Mt. Hebo Lake. I witnessed it in as described on other side. These are described but are not original.

I cannot accept this for original corner evidence, but put in the record for others guidance.

2/5/36 [illegible]

U. S. GOVERNMENT PRINTING OFFICE: 1936 8—7394

T. R. Mer.

(Make sketch of topography near Corner)

Sec. Sec. Sec. Sec.

#691