


TILLAMOOK COUNTY REWITNESS #780

(W) SEC.

COR. 27 T 4S R 10 W., WM.

(S) GLO Page 26

HISTORICAL: Book 4 Page 96 ± 1956

| | | |
|---|---|---|
| Triple Stump | S 49° E | 285 |
| 2" IP fence Cor. | S 24° 46' W | 321 |
| 2" IP fence Cor | N 8° W | 488 |
| Book 3 Pg 377 | Book 3 Pg 230 | BK 1 Pg 83 |

Book 53 Page 34 // BK 5 Pg 155 // MAP A-115 & A-316 A-2090

ALL GLO B.T.'s ARE GONE

FOUND: 1 1/4" IP + 4" deep in US 101 blacktop

| CONDITION | | | |
|---|---|---|---|
| not useable. | stump remains | S 49° E | ± 285 (Field ± 1972) |
| * good | 2" IP fence Cor | S 24° 46' W | 3214 = 3214 |
| * good | 2" IP fence Cor | N 8° W. | 488 = 4882 |
| good (USFS) | 4" x 4" x 84 Post | ± N 8° W | ± 488 |

Found 2 1/2" Iron Pipe with 3" Brass Cap South 13/4 Which is Witness Corner set by R.S. 920 in 1970. BK 3 Pg 377

COMMENTS: * = Tillamook County Corner Tag Placed.

~ Fd Steel Fence Post set ~ by R.S. 920 at Witness ~ Corner.

REWITNESS

I SET 1 1/4" Iron Rebar with 3" Brass Cap in Concrete inside found 1 1/4" I.P.

S 3° E feet 128

*96 " Hat Section S. E.




NEW ACCESSORY:

| | | |
|---|---|---|
| X in top RR iron @ | S 76° E | 2993 |
| S gate post of school | | |
| Top Fire hydrant in front of school | N 55° E | 15689 |

SET Hat Section N4-W4½ Gale Arthur Dan McNutt 12-27-73

COMMENTS: No hat section or post erected as USFS already has 4" x 4" x 84" Section line Crossing post erected. THE F.D. BRASS CAP WAS SET IN CONCRETE

T4S R10W S28 S27 S33 S34 RS287 1972 5/72 GA RK

IN THE PRESENCE OF: Allan E Duncan

John L Conlin

DATE: 8/67 PHOTO#: Count Surveyor TITLE GWA

* = County corner tag affixed.