

SURVEY IN THE N.W. QUARTER OF SECTION 1, AND
THE N.E. & S.W. QUARTERS OF SECTION 2,
TOWNSHIP 3 NORTH, RANGE 9 WEST, W.M.

FOR: GOD'S VALLEY TIMBER CO., LONGVIEW FIBRE CO.,
& STATE OF OREGON

BY: KARL F. FOESTE
361 S. W. MAIN COURT
WARRENTON, OREGON 97146

SEE MAP B-3516

DATE: July 12, 1994

NOTE: See my survey plat recorded as a part of this narrative.

NARRATIVE: Purpose of survey is to blaze and monument those boundaries shown thus ////////// on the annexed survey plat.

In 1966 the Oregon State Board of Forestry subdivided the subject sections 1 and 2. The State's survey is recorded as County Survey B-510. The quarter corner common to Sections 3 and 34, accepted by the State and recorded in Tillamook County Rewitness Book 2, Page 595 and Book 6, Page 249, does not monument the original position of said corner as established by G.L.O. surveyor Manius Buchanan in 1891. The original position for this corner was restored by me in April 1983. My restoration of this corner is recorded in Tillamook County Rewitness Book 7, Page 225. In August 1983, Richard Morris, PLS 401, made a survey that disputes my restored position. Morris' survey is recorded as Tillamook County Survey B-1138. I have examined Morris' survey, but with all due respect, I disagree with almost every finding reported on his survey; most specifically, his depiction of the location of the creek reported by Buchanan in 1891 as "touch N. edge of creek same as last given" at 3.5 chains west of the subject quarter corner. Morris' survey shows the creek crossing the section line at 240 feet and 340 feet west of the quarter corner restored by me. The creek does not cross the section line, and in the vicinity of this call, its channel has not moved since Buchanan reported its position in 1891. Evidence of the channel not moving is supported by the fact that the creek banks are lined with undisturbed stumps of trees that were present in 1891. In April of 1996, Tillamook County Surveyor Allan Duncan, Clatsop County

Surveyor Steven Thornton, and Oregon State Board of Forestry surveyor Anthony Klosterman made a field examination of the subject quarter corners. Both County Surveyors and Mr. Klosterman accepted the corner position restored by me in 1983. Acceptance of my corner by the two County Surveyors is evidenced by that report recorded in Tillamook county Rewitness Book 7, Page 225-C, and Clatsop County B.T. Record 2201. Acceptance of my corner position by the State is evidenced by that letter granting permission to remove existing corner monuments. Said letter is recorded in Tillamook County Rewitness Book 7, Page 613, and Clatsop County B.T. Record 2201.

In executing their survey of Sections 1 and 2, the State ignored the five large line trees reported on line between the quarter corner common to Section 3 and 34, and the quarter corner common to Sections 1 and 36. I have found four of the five line trees, and as is shown on the annexed plat, the distances between them agree closely with the distances reported by Buchanan. They are all the correct species, and given allowances for time, their diameters are within acceptable limits and their positions agree well with the G.L.O. topographic calls. There are no other qualified candidates within a 50-foot radius of each identified line tree. There were no notches found on any of the line trees, but the absence of notches can be explained by the loss in diameter due to decay and the passage of time. The physical evidence of each tree, and the corroborative evidence of distances between them, their positions relative to G.L.O. topography calls, and their close position (offset distance) from the line between found original quarter corners common to Sections 36 and 1, and 34 and 3, definitely identifies each of the found subject trees as original line trees. Section 5-18 of the Manual of Surveying Instructions 1973 prescribes: "Under the law, a definitely identified line tree is a monument of the original survey. It properly is used as a control point in the reestablishment of lost corners by the appropriate method of proportionate measurement."

I do not accept the State's survey of the subject Sections 1 and 2 because it is based on an erroneous quarter corner and the State did not incorporate the G.L.O. line trees in the reestablishment of the lost north quarter corner and northeast and northwest corners of Section 2. I have removed the State's monuments as described in the attached Corner Narratives, and I have executed my survey of the subject Sections 1 and 2 as follows: Held position of found original G.L.O. quarter corners on the north boundaries of Sections 1 and 3, and the positions of the found G.L.O. line trees on the north boundaries of Sections 1, 2, and 3, and reestablished the intervening section corners and quarter corner by single proportionate measurement between said found corners and line trees as per Sections 5-18 and 5-34 of the Manual of Surveying Instructions 1973. Reestablished the northeast corner of Section 1 at a point located on the south boundary of Section 36 and at the record distance (as reported by G.L.O. surveyor Henry Meldrum on Sept. 26, 1891) of 116 links (76.56 ft.) west of the southeast corner of Section 36. Reestablished the lost corner common to Sections 1, 2, 11, and 12 as prescribed in Section 5-29 of the 1973 manual. Reestablished the lost east quarter corner to Section 1 as prescribed in Section 5-34 of the 1973 manual. Reestablished the lost south quarter corners to Sections 1 and 2 and the lost east and west quarter corners to Section 2 as prescribed in Section 5-38 of said manual. Held position of found and reestablished corners and subdivided Sections 1 and 2 as prescribed in Sections 3-87 and 3-89 of the 1973 manual.

Basis of bearings is true bearings as determined from observations of Polaris taken at latitude 45° 47.00' north and longitude 123° 44.33' west. Place of observation is at the brass cap monument set by the State of Oregon at an erroneous position for the corner common to Sections 1 and 2, T3N, R9W and Sections 35 and 36, T4N, R9W, W.M. Said monument bears N 05°21' W 17.77 feet from monument 161 set by me at the correct position for said corner.

DESCRIPTION OF FOUND AND SET MONUMENTS

Note: Bearing trees scribed by me are scribed as directed in Sections 4-102 and 4-106 of the "Manual of Surveying Instructions 1973". Unless otherwise noted, all bearings reported to bearing objects are hand compass bearings using a declination of 21-1/2° east. Unless otherwise noted, distances reported to bearing trees scribed by me are to a nail in a 3/4" brass disk stamped "LS 849" set in a scribed letter "B". Alder trees are bark scribed. Aluminum monuments set by me also have a "DEEP-1" magnet inserted in the pipe.

LEGEND:

- C.P. = 6' long orange Carsonite post with white "SURVEY MONUMENT" sticker
- C.S. = County Survey
- G.I.P. = galvanized iron pipe
- O.S.B.F = Oregon State Board of Forestry
- S.O.D.F = State of Oregon Department of Forestry
- Y.P.C. = yellow plastic cap

- 73. At the quarter corner common to Sections 3 and 34, T3 and 4N, R9W, W.M. I find a 3" brass cap and B.T.'s as recorded on Clatsop County B.T. Record 827 and Tillamook County Rewitness Book 7, Page 225. The 12" hemlock B.T. at S75°E 5.10 feet is now 16" with partially overgrown face. The 20" alder B.T. at N03°W 45.30 feet is still 20". The original 44" cedar B.T. at S79°30'W 17.16 feet is still standing. The 3" brass cap at the erroneous quarter corner reported by the State in 1966 on Clatsop County Surveys C-777 and B-7828, and Tillamook County Survey B-510 bears N17°15'E 36.62 feet. The State's corner is also recorded in Tillamook County Rewitness Book 2, Page 595 and Book 6, Page 249. Date: 7/12/94.
- 114. At the quarter corner common to Sections 1 and 36, T3 and 4N, R9W, W.M. I find a 3" brass cap on 1-1/2" iron pipe as recorded on Clatsop County B.T. Record 273-19 and Tillamook County Rewitness Book 3, Page 29. The 22" fir B.T. at N48°45'E 70.0 feet is cut and buried in logging slash. The 7" spruce B.T. at S11°30'E 15.8 feet is now 18" with overgrown face. The 16" fir stump at S04°W 27.7 feet is still present with scribes visible. Date: 7/12/94
- 151. Found original 50" spruce line tree reported at 12.25 chains east of quarter corner common to Sections 3 and 34, T3 and 4N, R9W, W.M., now a 6 foot tall spruce stump 55" in diameter with bark and sapwood gone. I set R.P.'s which bear as follows from the center of this stump: a 5/8" x 36" rebar with Y.P.C., top flush with ground, bears N17°11'W 10.23 feet; and a 5/8" x 36" rebar with Y.P.C., top flush with ground, bears N88°22'W 10.00 feet. Date: 7/13/94
- 152. Found original 96" spruce line tree reported at 29.25 chains east of section corner common to Sections 2, 3, 34 and 35, T3 and 4N, R9W, W.M., now a 96" diameter spruce snag 6 feet tall on the west side, the east side has fallen. I set R.P.'s which bear as follows from the center of this line tree: a 5/8" x 36" rebar with Y.P.C., top flush with ground, bears S00°29'E 9.69 feet; a 5/8" x 36" rebar with Y.P.C., top flush with ground, bears N89°10'W 10.00 feet. Date: 7/13/94
- 155. Found original 100" spruce line tree reported at 5.00 chains east of the quarter corner common to Sections 2 and 35, T3 and 4N, R9W, W.M., now a rotten spruce stump approximately 100" in diameter and 3' to 4' tall. I set

R.P.'s which bear as follows from the center of this line tree: a 5/8" x 36" rebar with Y.P.C., top flush with ground, bears N89°50'W 10.00 feet; a 5/8" x 36" rebar with Y.P.C., top flush with ground, bears S89°25'E 10.00 feet. Date: 7/13/94

156. Found original 72" fir line tree reported at 32.50 chains east of section corner common to Sections 1, 2, 35 and 36, T3 and 4N, R9W, W.M., now a burned and rotten fir stump about 5 feet in diameter without bark, top flush with ground on west side and about 4 feet above ground on east side. I set R.P.'s which bear as follows from the center of this line tree: a 5/8" x 36" rebar with Y.P.C., top 3" below ground, bears N89°25'W 10.00 feet; a 5/8" x 36" rebar with Y.P.C., top 6" below ground, bears S89°39'E 10.00 feet. Date: 7/13/94
159. Section corner common to Sections 2, 3, 34 and 35, T3 and 4N, R9W, W.M. At single proportioned position between found line trees 151 and 152 I set flush with ground a 2" x 36" G.I.P. with 3" fully stamped brass cap, from which I scribed the following B.T.'s: a 12" alder bears N44°E 20.05 feet, a 21" fir bears S72°E 26.00 feet; an 18" alder bears S08°W 15.83 feet; and a 28" fir bears N67°W 34.3 feet. The 3" brass cap at the erroneous section corner established by the State, recorded on Clatsop County Survey 777 and Tillamook County Survey B-510, bears N17°56'W 46.05 feet. Date: 7/13/94
160. Quarter corner common to Section 2 and 35, T3 and 4N, R9W, W.M. At single proportioned distance between found line trees 152 and 155 I set a 2" x 36" G.I.P. with a 3" fully stamped brass cap, top 2" below ground, from which I scribed the following B.T.'s: an 11" spruce bears N38°E 31.40 feet; a 14" spruce bears S62°E 11.75 feet; an 8" spruce bears S37°W 25.27 feet; a 4" spruce, with "X" chopped at breast height, bears N34°W 17.40 feet to face scribed "BT". The 3" brass cap at the erroneous quarter corner established by the State, recorded on Clatsop County Survey C-777 and Tillamook County Survey B-510, bears N26°31'10"W 37.92 feet. I did not remove the State's monument. Date: 7/13/94

On Sept. 24, 1996, I find that the above described corner monument and the southeast and northwest bearing trees have been destroyed by construction of a dirt logging road. In former position of said monument I set a 2" X 36" concrete filled G.I.P. with a 3" fully stamped brass cap, top 8" below road surface, from which I scribed two new B.T.'s: a 10" spruce bears S38°E 13.31 feet and a 14" hemlock bears N82°W 76.74 feet. Set 6' metal fence post with location tag 12" south of corner on south side of road.

161. Section corner common to Sections 1, 2, 35 and 36, T3 and 4N, R9W, W.M. At single proportioned position between found line trees 155 and 156 I set a 2" x 36" G.I.P. with a 3" fully stamped brass cap, top 10" below ground, from which I set 5/8" x 36" rebars with Y.P.C.'s, tops 8" to 10" below ground, as follows: N29°00'E 35.06 feet, S50°35'E 14.75 feet, S48°18'W 30.31 feet, and N44°12'W 37.95 feet. The center of the eastern steel gate post on north side of God's Valley Road bears S15°04'E 134.6 feet. The 3" brass cap at the erroneous section corner established by the State, recorded on Clatsop County Survey C-777 and Tillamook County Survey B-510 bears N 05° 21' W 17.77 feet. I did not remove the State's monument. Date: 7/13/94
170. At the West Sixteenth corner common to Sections 2 and 35, T3 and 4N, R9W, W.M. I set 2" x 36" G.I.P. with fully stamped 2-5/8" brass cap, top flush with ground, from which I scribed the following B.T.'s: a 12" spruce

bears N20°E 18.65 feet and a 13" spruce bears S80°W 7.00 feet. The 3" brass cap at the erroneous W 1/16 corner set by the State in 1966 and reported on Clatsop and Tillamook County Surveys 777 and B-510, respectively, bears N19°49'W 46.18 feet. Date: 7/13/94

191. At the West Sixteenth corner common to Sections 1 and 36, T3 and 4N, R9W, W.M. I set a 2" x 36" G.I.P. with 3" fully stamped brass cap, top flush with ground, from which I scribed one new B.T. as follows: a 14" fir bears N20°W 32.9 feet. Bearing trees scribed by State in 1966 and recorded on Clatsop County Survey C-777 and Tillamook County Survey B-510 bear as follows: a 15" fir stump N01°E 17.80 feet to face scribed "BT"; a 23" fir S70°W 5.20 feet to overgrown face. The brass cap monument set at the erroneous sixteenth corner established by the State bears N06°37'W 10.42 feet. Date: 6/12/94
498. At the southeast corner of Section 36, T4N, R9W, W.M. I find 1-1/2" G.I.P. with 3" bronze cap in mound of stone set by Harold Russell in 1965 and recorded in Clatsop County B.T. Record 273-20 and Tillamook County Rewitness Book 7, Page 182. All original B.T.'s are no longer present, but the B.T.'s scribed by Russell bear as follows: the 28" spruce at N86°15'W 89.2 feet is now a 48" spruce with overgrown face; the 30" hemlock at N36°45'W 90.4 feet is now a 40" hemlock with overgrown face. I bark scribed four new B.T.'s as follows: an 8" alder bears S40°W 7.85 feet; an 8" alder bears N72°E 12.00 feet; and a 9" alder bears S08°E 20.00 feet. Set 5' long white fiberglass fence post 2' east. Reset Russell's white 4" x 4" cedar post 1.0 feet northwest. Date: 3/10/95
562. At the section corner common to Sections 2, 3, 10, and 11, T3N, R9W W.M., I find a 3-3/4" aluminum S.O.D.F. cap, fully stamped, on a 1-1/2" aluminum pipe, top flush with ground, from which B.T.'s established by the State, recorded in Tillamook County Rewitness Book 6, Page 337, bear as follows: the 29" fir at S22°E 42.6 feet is now a 34" fir with overgrown face; the 34" hemlock at S61-1/2°W 37.2 feet is now a 38" tree with partially overgrown face. The 15" hemlock at S70°W 37.7 feet, origin unknown, is now a 20" tree with scribed "10" exposed. The 15" hemlock at N82°E 2.3 feet reported by the State is now 18". The 22" badly rotted stump, that the State calls the original 7" hemlock at N55°E 18 lks set by Buchanan, is not the original B.T., there being no scribing found. I find Buchanan's 8" hemlock at S08°E 26 lks. to now be a 38" badly rotted stub that bears S10°E 16.70 feet. His 10" hemlock at S70°W 71 lks. is now a rotted mound. The 15" hemlock at N25°W 53 lks. is gone. Date: 9/5/94
564. At the 1/4 corner common to Sections 2 and 3, T3N, R9W, W.M., I set a 3-3/4" aluminum S.O.D.F. cap, fully stamped, on a 1-1/2" x 30" aluminum pipe, top 3" above ground, from which B.T.'s established by the State, recorded on Clatsop County Survey C-777 and Tillamook County Survey B-510, bear as follows: the NW B.T. is now a 62" double hemlock with overgrown face that bears N07°W 56.80 feet to a 3/4 brass disk, stamped "LS 849"; the SE B.T. is now a 50" hemlock with overgrown face. This tree bears N48°E 7.35 feet to a face I scribe on its SW side. I also scribed a 50" spruce that bears S14°E 31.00 feet, and a 9" hemlock that bears S40°W 26.5 feet. The 3" O.S.B.F. bronze cap corner monument set by the State bears N15°23'W 20.06 feet. I removed this monument. Set 6' steel fence post with location poster 2' west of corner. Date: 9/12/96
645. At the closing section corner common to Sections 1 and 12, T3N, R9W, W.M., I find a 3" O.S.B.F. bronze cap,

fully stamped, on a 1-1/2" galvanized iron pipe, top 4" above ground, from which B.T.'s established by the State, recorded in Tillamook County Rewitness Book 2, Page 554, bear as follows: the 7" hemlock at S70°W 4.0 feet is now an 8" snag, 7 feet tall, with partially overgrown face; the 30" hemlock at N38°W 19.6 feet is now 34" with overgrown face and metal location poster; the 20" hemlock at N26°E 16.0 feet is now 23" with overgrown face. The 4" x 4" white painted cedar post is still present. Date: 7/24/96

648. At the township corner common to Section 31, T4N, R8W, and Section 6, T3N, R8W, W.M., I find a 3" O.S.B.F. bronze cap, fully stamped, on a 1-1/2" galvanized iron pipe, top 3" above ground, from which B.T.'s established by the State, recorded in Tillamook County Rewitness Book 3, Page 30, bear as follows: the 18" fir at S20-1/4°W 13.3 feet is now 21" with overgrown face and metal location poster; the 19" fir at S30°E 29.0 feet is now 28" with overgrown face; the 13" fir at N67°E 2.9 feet is now 16" with overgrown face. The 5" x 5" scribed cedar post set by P.L. Thompson is now gone. Thompson's 14" fir at N25°E 16.6 feet is now a 23" tree. The 4" x 4" white painted cedar post is still present. I set a C.P. 2' north of corner. Date: 7/24/96
650. At the section corner common to Sections 11, 12, 13, and 14, T3N, R9W, W.M., I find a 3" O.S.B.F. bronze cap, fully stamped, on a 1-1/2" galvanized iron pipe, top 4" above ground, from which B.T.'s established by the State, recorded in Tillamook County Rewitness Book 2, Page 593, bear as follows: the 10" fir at S76°W 16.7 feet is now a dead 12" snag; the 17" fir at N18-1/2°E 30.2 feet is now 28" with overgrown face; the 12" fir at S36-1/4°E 24.5 feet is now 21" with overgrown face; the 11" fir at N17-3/4°W 111.3 feet is now a blown down 14" tree. Date: 7/25/96
654. At the section corner common to Sections 1, 2, 11, and 12, T3N, R9W, W.M., I set a 3-3/4" aluminum S.O.D.F. cap, fully stamped, on a 1-1/2" x 30" aluminum pipe, top flush with ground, from which B.T.'s established by the State, recorded on Clatsop County Survey C-777 and Tillamook County Survey B-510, bear as follows: the NE B.T. is now a 13" spruce stump, with scribing visible, that bears N25°E 23.30 feet; the SE B.T. is now a 30" hemlock stump, with scribing visible, that bears S55°E 13.40 feet; the SW B.T. is now a 51" cedar stump with scribing visible, that bears N45°W 13.10 feet. I scribed the following B.T.'s: a 9" hemlock bears N26°E 18.20 feet; a 9" hemlock bears S62°E 23.86 feet; a 15" fir bears S74°W 28.08 feet; an 8" hemlock bears N56°W 9.70 feet. The 3" O.S.B.F. bronze cap corner monument set by the State bears N01°55'W 10.56 feet. I removed this monument. Set C.P. 2' north of corner. This corner lies on a very steep northern slope, 11 feet north of the north edge of Rector Ridge Road. Date: 9/11/96
655. At the 1/4 corner common to Sections 2 and 11, T3N, R9W, W.M., I set a 3-3/4" aluminum S.O.D.F. cap, fully stamped, on a 1-1/2" x 30" aluminum pipe, top flush with ground, from which B.T.'s established by the State, recorded on Clatsop County Survey C-777 and Tillamook County Survey B-510, bear as follows: the NW B.T. is now an 11" hemlock with partially overgrown face that bears N16°W 13.68 feet to a 3/4" brass disk, stamped "LS 849", set in the face; the SE B.T. is now a 26" fir with overgrown face that bears S54°E 28.78 feet to a 3/4" brass disk stamped "LS 849". I scribed the following B.T.'s: a 16" hemlock bears S20°E 2.70 feet; a 26" fir bears N24°E 21.8 feet. The 3" O.S.B.F. bronze cap corner monument set by the State bears N09°53'W 5.93 feet. I removed this monument. Set C.P. 2' north of corner, and a 4" x 4" cedar post 2' west. Date: 9/9/96

656. At the 1/4 corner common to Sections 1 & 12, T3N, R9W, W.M., I set a 3-3/4" aluminum S.O.D.F. cap, fully stamped, on a 1-1/2" x 30" aluminum pipe, top flush with ground, from which B.T.'s established by the State, recorded on Clatsop County Survey C-777 and Tillamook County Survey B-510, bear as follows: the NE B.T. is now a 17" fir that bears N46°E 29.05 feet to a 3/4" brass disk, stamped "LS 849", set in the overgrown face; the SE B.T. is now a 25" fir, with face and lower 3 feet of tree buried by road fill, that bears S25°E 36.14 feet to center of tree at 5' above ground on the uphill side. I scribed the following B.T.'s: a 20" fir bears S68°E 61.05 feet; a 20" fir bears S42°W 48.76 feet; a 26" fir bears N85°W 28.50 feet. The 3" O.S.B.F. bronze cap corner monument set by the State bears N02°05'W 4.11 feet. I removed this monument. Set C.P. 2' north of corner. This corner lies on the north edge of Rector Ridge Road, at the base of the road cut. Date: 9/11/96
657. At the 1/4 corner common to Sections 1 and 2, T3N, R9W, W.M., I set a 3-3/4" aluminum S.O.D.F. cap, fully stamped, on a 1-1/2" x 30" aluminum pipe, top flush with ground, from which B.T.'s established by the State, recorded on Clatsop County Survey C-777 and Tillamook County Survey B-510, bear as follows: the NE B.T. is now a blown down 20" hemlock that bears N15°E 60.0 feet; the SW B.T. is now a 36" spruce stump with scribing visible that bears S62°W 57.30 feet. I scribed the following B.T.'s: an 18" hemlock bears N35°E 12.57 feet; an 18" hemlock bears S27°E 48.50 feet; a 20" hemlock bears S38°W 15.32 feet; a 14" spruce bears N82°W 50.70 feet. The 3" O.S.B.F. bronze cap corner monument set by the State bears N00°24'E 13.41 feet. I removed this monument. Set C.P. 2' east of corner, and a 4" x 4" cedar post 0.5' west. Date: 9/5/96
658. At the northeast corner of Section 1, T3N, R9W, W.M., I set a 3-3/4" aluminum S.O.D.F. cap, fully stamped, on a 1-1/2" x 30" aluminum pipe, in a rock mound, top 2" above ground; from which B.T.'s established by the State, recorded on Clatsop County Survey C-777 and Tillamook County Survey B-510, bear as follows: the SE B.T. is now a blown down 30" spruce with overgrown face; the SW B.T. is now a 26" spruce stump with overgrown face that bears S27°W 35.9 feet to face scar on top of the stump. I scribed the following B.T.'s: a 12" alder bears N35°E 22.30 feet; a 6" hemlock bears S22°E 3.63 feet; a 4" fir, with an "X" chopped at breast height, bears S48°W 21.48 feet to a 3/4" brass disk, stamped "LS 849", in face scribed "BT"; a 43" spruce bears N69°W 12.65 feet. The 3" O.S.B.F. bronze cap corner monument set by the State bears east 1.14 feet. I removed this monument. Set C.P. 2' south of corner, and a 4" x 4" white painted cedar post 2' north. Date: 10/2/96
659. At the C 1/4 corner of Section 2, T3N, R9W, W.M., I set a 3-3/4" aluminum S.O.D.F. cap, fully stamped, on a 1-1/2" x 30" aluminum pipe, top flush with ground, from which B.T.'s established by the State, recorded on Clatsop County Survey C-777 and Tillamook County Survey B-510, bear as follows: the NW B.T. is now a 48" spruce stump with overgrown face that bears N27°W 87.6 feet; the NE B.T. is now a 27" rotten spruce stump with scribing visible that bears N46°E 70.5 feet. I scribed the following B.T.'s: a 56" double spruce bears N64°E 67.4 feet; an 16" hemlock bears S78°E 44.6 feet; an 18" hemlock bears S02°E 47.17 feet; a 10" alder bears N76°W 30.94 feet. The 3" O.S.B.F. bronze cap corner monument set by the State bears N23°49'W 18.41 feet. I removed this monument. Set C.P. 2' north of corner. Date: 9/9/96

660. At the N 1/16 corner common to Sections 1 and 2, T3N, R9W, W.M., I set a 3-3/4" aluminum S.O.D.F. cap, fully stamped, on a 1-1/2" x 30" aluminum pipe, top flush with ground, from which I scribed the following B.T.'s: a 20" hemlock bears N56°E 22.33 feet; an 8" alder bears N78°W 19.80 feet. Set C.P. 2' north of corner. Date: 9/5/96
661. At the C-N 1/16 corner of Section 2, T3N, R9W, W.M., I set a 3-3/4" aluminum S.O.D.F. cap, fully stamped, on a 1-1/2" x 30" aluminum pipe, top flush with ground, from which I scribed the following B.T.'s: a 12" alder bears N01°E 21.38 feet; an 18" double spruce bears S54°W 37.10 feet. Set C.P. 2' north of corner. This corner lies 50' +/- south of God's Valley Creek and 200' +/- north of God's Valley Road. Date: 9/5/96
662. At the C-S 1/16 corner of Section 2, T3N, R9W, W.M., I set a 3-3/4" aluminum S.O.D.F. cap, fully stamped, on a 1-1/2" x 30" aluminum pipe, top flush with ground, from which B.T.'s established by the State, recorded on Clatsop County Survey C-777 and Tillamook County Survey B-510, bear as follows: the SE B.T. is now a 30" spruce stump with scribing gone that bears N80°E 20.75 feet; the SW B.T. is now a 37" hemlock stump with scribing gone that bears S76°W 25.8 feet. I scribed the following B.T.'s: an 18" hemlock bears N82°E 4.6 feet; a 12" fir bears N28°W 21.6 feet. The 3" O.S.B.F. bronze cap corner monument set by the State bears N21°09'W 11.40 feet. I removed this monument. Set C.P. 2' north of corner. Date: 9/9/96
663. At the C-W 1/16 corner of Section 2, T3N, R9W, W.M., I set a 3-3/4" aluminum S.O.D.F. cap, fully stamped, on a 1-1/2" x 30" aluminum pipe, top flush with ground. I scribed the following B.T.'s: a 14" hemlock bears S84°W 24.5 feet; a 3" fir bears S60°W 24.03 feet to a 3/4" brass disk, stamped "LS 849", set in face scribed "BT". I chopped an "X" at breast height on this tree. Set 6' steel fence post with location poster 2' north of corner. Date: 9/12/96
665. At the W 1/16 corner common to Sections 2 and 11, T3N, R9W, W.M., I set a 3-3/4" aluminum S.O.D.F. cap, fully stamped, on a 1-1/2" x 30" aluminum pipe, top flush with ground, from which B.T.'s established by the State, recorded on Clatsop County Survey C-777 and Tillamook County Survey B-510, bear as follows: the SE B.T. is now a 12" fir snag, 12 feet tall, with overgrown face that bears S05°E 5.75 feet; the NW B.T. is now a 10" fir stump with overgrown face that bears N20°W 31.57 feet. I scribed the following B.T.'s: an 8" hemlock bears N88°E 11.70 feet; a 34" fir bears S08°W 9.18 feet. The 3" O.S.B.F. bronze cap corner monument set by the State bears N12°27'W 3.27 feet. I removed this monument. Set C.P. 2' north of corner, and a 4" x 4" cedar post 2' west. Date: 9/24/96
666. At the SW 1/16 corner of Section 2, T3N, R9W, W.M., I set a 3-3/4" aluminum S.O.D.F. cap, fully stamped, on a 1-1/2" x 30" aluminum pipe, top 2" below ground, from which B.T.'s established by the State, recorded on Clatsop County Survey C-777 and Tillamook County Survey B-510, bear as follows: the SE B.T. is now a 27" fir stump, with scribing gone, that bears S72°E 8.60 feet; the SW B.T. is now a 14" hemlock snag, 8 feet tall, with overgrown face, that bears N72°W 18.0 feet. I scribed the following B.T.'s: a 12" fir bears S18°E 19.87 feet; a 16" hemlock bears S76°W 13.45 feet. The 3" O.S.B.F. bronze cap corner monument set by the State bears N19°04'W 12.11 feet. I removed this monument. Set C.P. 2' north of corner. Date: 7/12/96

668. At the C-W 1/16 corner of Section 1, T3N, R9W, W.M., I set a 3-3/4" aluminum S.O.D.F. cap, fully stamped, on a 1-1/2" x 30" aluminum pipe, top flush with ground, from which B.T.'s established by the State, recorded on Clatsop County Survey C-777 and Tillamook County Survey B-510, bear as follows: a 31" fir bears S80°E 31.0 feet to overgrown face; a 27" fir bears N53°E 35.60 feet to overgrown face. I scribed the following B.T.'s: a 24" hemlock bears S32°W 12.08 feet; a 19" spruce bears N11°W 21.10 feet. The 3" O.S.B.F. bronze cap corner monument set by the State bears N03°02'E 11.45 feet. I removed this monument. Set C.P. 2' north of corner, and a 4" x 4" cedar post 2' west. Date: 9/5/96
670. At the NW 1/16 corner of Section 1, T3N, R9W, W.M., I set a 3-3/4" aluminum S.O.D.F. cap, fully stamped, on a 1-1/2" x 30" aluminum pipe, top flush with ground, from which I scribed the following B.T.'s: a 14" spruce bears S77°E 9.40 feet; a 12" hemlock bears S42°W 23.10 feet. Set C.P. 2' north of corner. Date: 9/5/96
671. At the E 1/4 corner of Section 1, T3N, R9W, W.M., I set a 3-3/4" aluminum S.O.D.F. cap, fully stamped, on a 1-1/2" x 30" aluminum pipe, top 6" below ground, from which B.T.'s established by the State, recorded on Clatsop County Survey C-777 and Tillamook County Survey B-510, bear as follows: the SW B.T. is now a 24" fir that bears S39°W 11.10 feet to a 3/4" brass disk, stamped "LS 849", in the top of the overgrown face; the NW B.T. is now a 17" hemlock that bears N36°W 46.70 feet to a 3/4" brass disk, stamped "LS 849", in the top of the overgrown face. I scribed the following B.T.'s: a 20" fir bears N12°E 20.03 feet; a 26" fir bears S87°E 7.50 feet. The 3" O.S.B.F. bronze cap corner monument set by the State bears N61°27'W 0.56 feet. I removed this monument. Set C.P. 2' north of corner, and a 4" x 4" cedar post 2' south. Date: 9/24/96

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

Karl F. Foeste

**OREGON
JULY 12, 1968
KARL F. FOESTE
0849**

Renews 1/1/2014

