

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One Quarter corner common to Sections 26 and 35,
TLN, R10W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (missing, point falls on N.E. root of a 36" Spruce) from which a:

60" Hemlock bears N24W 23 lks.; now 50" rotted stub, face and scribes
rotted away.

24" Hemlock bears S52W 23 lks.; now 24" rotted stub, scribes and face
rotted away.

10 lk. Cr. course SW, bears East 2.96 chs.; now in place.
Three original line blazes East of corner point.

RESTORED

Scribed North side of Spruce root 1/4 and X at corner point, from which a:

24" Hemlock bears N79 1/2 E 32.2 ft.; scribed 1/4 S26 BT RS401.

23" Hemlock bears S52 1/2 E 13.3 ft.; scribed 1/4 S35 BT.


Oregon State Board of Forestry metal location poster on new 24" Hemlock B.T.
Set 4" x 4" x 56" white painted Cedar post 2.0 ft. N.E. of pipe.

Dated July 13, 1959

Restored by



Richard A. Morris



Present and witnessed by H. Russell
R. Cop