

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One Quarter corner common to Sections 22 and 27,
T1N, R10W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (missing) from which a:

- 24" Hemlock bears North 42 lks.; portion of badly rotted stump in place.
- 64" Hemlock bears S36E 39 lks.; now rotted stub 2' high, face and scribes rotted away.

RESTORED October 4, 1886 by Hayes

Post, Fir limb (missing) from which a:

- 18" Hemlock bears North 42 lks; (see above)
- 9" Hemlock bears S67W 47 lks; now 37" stub, scribes 1/4 S BT visible.

RESTORED

Var. 21 1/2°


Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S22 S27 1959 RS401", 34 inches in ground, and from which a:

- 12" Hemlock bears S62 1/2 W 7.4 ft.; scribed 1/4 S27 BT RS401.
- 24" double Hemlock bears N60 1/2 E 52.7 ft.; scribed 1/4 S22 BT.


Oregon State Board of Forestry metal location poster on 12" Hemlock BT.
Set 4" x 4" x 56" white painted Cedar post 1.0 foot N.W. of pipe.

Dated August 4, 1959

Restored by Harold J. Russell under my direction.
Harold Russell, Engineering Tech. I



Richard A. Morris



Present and witnessed by E. Nylund
D. Jones