

N. Com. Y6
27-1. N. 10. Cor

CHAINS

RECOVERY AND RESTORATION of the NC 1/16 corner of Section 27,
T 1 N, R 10 W, W.M.

On October 14, 1960, I ran South out of the $\frac{1}{4}$ corner of Sections
22 and 27, T 1 N, R 10 W, W.M. (Restored by O.S.B.F. July 9, '59)
1303.8 feet and found:

Old BT 43" Hemlock. I chopped into this and exposed 50 yr.
old scribing "/16S".

Old BT 28" Hemlock. I chopped into this and exposed old
scribing "BT".

In the presence of: George L. Hieber

Returned to area on December 7, 1960, with copy of County
Surveyors Notes, dated January, 1923, calling for:

BT 43" Hemlock N 0° 11.5 feet distant
BT 28" Hemlock N 88° E 21.0 feet distant

I set Hemlock post 11.5 feet distant N 1° W (var. 23° E) and
21.0 feet distant N 81° E to the respective BT's.

In the presence of: Robert T. Reed

Returned to area July 17, 1962, and set a 1" galvanized iron
pipe with a lead plug, 6" out of the ground, in place of the
Hemlock post. I then reset the Hemlock post 1.0 feet West of
the iron pipe.

The top of the lead plug is marked as follows:

In the presence of: Troy K. Moore

July 20, 1962

I, Roswell K. Miller, hereby certify
that this corner was restored by me,
from the original notes of the County
Surveyor, under the supervision of
Charles G. Collard, Registered Land
Surveyor, State of Oregon # 376

Roswell K. Miller

Roswell K. Miller