

(40)

CHAINS  
FEET

Restoration for the Oregon State Board of Forestry of the Corner to Sections 28-29-32 & 33, T 2N, R 6W, W.M. Tillamook County, Ore. March 29, 1950

Using a K & E Light Mtn. Transit, with a magnetic variation 22° E The point for the corner to Sections 28-29-32 & 33 is determined by the remains of the original bearing trees:

A fir stump, 38" in diameter, bears N 81° W, a distance of 57.4 ft; scribe marks S & 9 plainly visible, but the 2 has been obliterated by axe marks.

A rotted fir stump, 32" in diameter, bears N 52° 15' E, a distance of 32.3 ft. No marks remain.

The roots of a fir, bear S 56° 15' W, a distance of 59.4 ft.

No evidence was found of the 24" hemlock bearing tree, the point for which falls in a recently constructed cat road.

At the corner point found roots of hemlock in ground

Set a 1½" iron pipe, 3 feet long, filled with charcoal, with an Oregon State Board of Forestry bronze cap stamped: T 2N, S 29 S 28 S 32 S 33, R 6W 1950 199.

from which:

A cedar snag, 42" in diameter, bears S 29° W, a distance of 94.1 feet, scribed R 6W, S 32 199.

A cedar snag 34" in diameter, bears N 58° E, a distance of 71.0 feet, scribed T 2N, S 28 199

A metal location poster on a fir stump, bears N 81° W, a distance of 57.4 feet, marked: Sec.29, T 2N, R 6W, Sec. Cor. 29-28-32 & 33 57.4 ft. S 81° E.

Present:

Don Davis  
Lyle Beyers

Lyle E. Beyers  
Forest Engineer

