

CHAINS
FEET

2541.2 The 1/4 corner between Sections 13 & 18 bears N 25°48' E
a distance of 71.2 ft.
The corner determined by a stone 30" x 24" x 20" marked 1/4

Continue North from 1/4 cor. bet. 13 & 18
Beginning new measurement.

1320 Set temp. stake.

2640 The corner to sections 12, 13, 7, 18 bears N 63°52' E
a distance of 29.1 ft.
The corner determined by an iron pipe 1 1/4 inches in diameter
and a stone 6" x 6" x 5" above ground with 4 notches on the
SW face and 2 notches on the NE face.

ADJUSTMENT OF TEMPORARY STAKES TO TRUE LINE POSITIONS BY
SINGLE PROPORTIONATE MEASUREMENT AND ESTABLISHMENT OF
MONUMENTS.

Relative to the compass bearing of the random line
the true line between the corner of sections 24, 25, 19 & 30
and the 1/4 cor. between secs. 19 & 24 bears N 0°18' E
a distance of 2636.3 ft.

I establish a witness corner to the corner of sections 24,
25, 19 & 30 T1N R 5 & 6 W by setting an iron pipe, 1 1/2 inches
in diameter 3 feet long, filled with charcoal, with an "Oregon
State Board of Forestry" bronze cap, West a distance of 5 feet
from the 4 1/2 inch fir snag which is the corner point. The bronze
cap is stamped: W.C. → E 5 T1N R6W R5W S24, S19, S25,
S30 1949 199

1318.1 Point for S 1/16 corner between secs. 24 & 19
Adjustment from temp. stake South 1.9 ft. East 6.0 ft.

Set an iron pipe 1 1/2 inches in diam. 3 ft. long, filled with
charcoal, with an Oregon State Board of Forestry bronze cap
stamped S 1/16 S24 S19 1949, 199

from which:

A fir snag 1 1/4 inches in diam. bears N 7° E
a distance of 21.6 feet scribed S 1/16 S19 199.

2636.3 The 1/4 corner between Secs. 19 & 24.
At the edge of the stone marking the 1/4 corner set an iron
pipe 1 1/2 inches in diam. 3 ft. long, filled with charcoal,
with an Oregon State Board of Forestry bronze cap stamped:
1/4 S24 S19 1949 199

(Continued on page _____)