

CHAINS FEET	from which:
	<p>A 4 inch X on a boulder 5' x 6' x 4' bears S 41° E a distance of 5.9 ft.</p> <p>A hemlock snag 39" in diam. bears N 20° W a distance of 41.5 ft. with a metal location poster.</p> <p>Relative to the compass bearing of the random line the true line from the 1/4 corner to Secs. 19 &amp; 24 to the 1/4 corner to Secs. 13 and 18 bears N 0° 17' E, a distance of 5248.9.</p> <p>Beginning new measurement</p>
1312.3	<p>Point for N 1/16 corner between Secs. 24 &amp; 19. Adjustment from temp. stake South 11.4 ft., East 18.8 ft.</p> <p>Set an iron pipe 1 1/2 inches in diam. 3 ft. long, filled with charcoal, with an Oregon State Board of Forestry bronze cap stamped N 1/16 S24, S19 1949 199</p> <p>from which:</p> <p>A metal location poster on a cedar snag 40 inches in diam. bears S 73° E, a distance of 40.5 ft.</p> <p>The corner is on the south side of bed of a stream, course N 45° E.</p>
2624.5	<p>Point for sec. cor. to Secs. 13, 24, 18, 19 T1N R5 &amp; 6 W WM. Adjustment from temp. stake South 19.2 ft., East 25.4 ft.</p> <p>Set an iron pipe 1 1/2 inches in diam. 3 ft. long, filled with charcoal, with an Oregon State Board of Forestry bronze cap stamped T1N R6W R5W S13 S18 S24 S19 1949 199</p> <p>from which:</p> <p>A fir stump 36 inches in diam. bears S 36° W a distance of 12.8 ft. Scribed S24 199.</p> <p>Continuing N 0° 17' E on same line between Secs. 13 &amp; 18. Beginning new measurement.</p>
1312.2	<p>Point for S 1/16 cor. to Secs. 13 &amp; 18. Adjustment from temp. stake South 27.0 ft., East 31.8 ft.</p> <p>Set an iron pipe 1 1/2 inches in diam. 3 ft. long, filled with charcoal, with an Oregon State Board of Forestry bronze cap stamped S 1/16 S13 S18 1949 199</p> <p>from which:</p> <p>A metal location poster on a fir snag 38 inches in diam. bears N 36° E, a distance of 30 ft.</p>

(Continued on page \_\_\_\_\_)