

Survey for the State of Oregon, Board of Forestry of the section line between Sections 5 and 8, Township 1 North, Range 5 West, W.M., Tillamook County, Oregon.

Beginning at the corner to sections 4, 5, 8, 9, Township 1 North, Range 5 West, W.M., determined by the remains of the original bearing trees:

The 18 inch hemlock, now 32 inches in diameter, has fallen. The scribe marks, R 5W, T 1N, are plainly visible. The stump hole bears North 54° East, a distance of 21.1 feet (32 lks)

A fir snag, 44 inches in diameter, with scribe marks BT plainly visible, bears South 70° East, a distance of 22.4 feet (34 lks). The field notes call for a distance of 24 lks. This falling does not agree with call of the other BT's, I therefor take the distance to be in error.

A hemlock stump, 12 inches in diameter, with scribe marks BT plainly visible, bears North 22° West, a distance of 39.6 feet (60 lks)

No evidence remains of the 4 inch hemlock BT.

At the point for the corner:

Set a stone 16 X 9 X 8 inches 5 inches in the ground with a cross (+) chiseled on the top side and 5 notches on the South edge and 4 notches on the East edge.

Place a mound of stones 18 inches high and 4 feet in diameter around the corner stone.

No suitable trees available for BT's.

Retracement:

Starting with a compass bearing, variation 22° East, using a K & E Light Mtn. transit.

Beginning at a point from which the corner to sections 4, 5, 8, 9, bears South 49° East, a distance of 14.5 feet. Run West on a random line between Sections 5 and 8

1325.6	Set temp. stake
1393	Road running North and South
1630	Stream 6 feet wide course North 15° East.
2651.2	Set temp. stake on top ridge running North and South. Find no evidence of the 1/4 corner.
3808	Stream 6 feet wide course North
4035	Road running North and South