

CHAINS	
1312.4	<p>Point for N 1/16 corner between sections 9 &amp; 10 by proportionate distance. Adjustment from temporary stake 1320.0 -- North 7.6 feet, West 13.0.</p> <p>At the point for corner</p> <p>Set a 1½ inch iron pipe, 3 feet long, with an Oregon State Board of Forestry bronze cap stamped: N 1/16 S9 S10 1950 199.</p> <p>from which:</p> <p>A fir, 14 inches in diam., bears N 53° W, a distance of 32.4 feet, scribed: N 1/16 S9 199.</p> <p>A hemlock, 15 inches in diam., bears S 33° 30' E, a distance of 71.6 feet, scribed: N 1/16 S 10 199.</p> <p>A metal location poster on the 14 inch fir BT is marked: Sec 9 T1N R7W N 1/16 Cor 31.8 ft S 53° E.</p>
2624.8	<p>Point for ¼ corner between sections 9 &amp; 10 by proportionate distance.</p> <p>Adjustment from temporary stake 2640.0 -- North 15.3 feet, West 26.0 feet.</p> <p>At the point for corner</p> <p>Set a 1½ inch iron pipe, 3 feet long, filled with charcoal, with an Oregon State Board of Forestry bronze cap stamped: ¼ S9 S10 1950 199.</p> <p>from which:</p> <p>An alder, 4 inches in diam., bears S 89° W, a distance of 31.0 feet, scribed: ¼ S9.</p> <p>An alder, 22 inches in diam., bears S 43° E, a distance of 61.0 feet, scribed: ¼ S10 199.</p> <p>Placed a metal location poster on the 4 inch alder BT &amp; marked it: Sec 10 T1N R7W ¼ Cor 31 FT N 89° E.</p>
3937.2	<p>Point for S 1/16 corner between sections 9 &amp; 10 by proportionate distance.</p> <p>Adjustment from temporary stake 3937.2 -- West 39.0 feet.</p> <p>At the point for corner</p> <p>Set a 1½ inch iron pipe, 3 feet long, filled with charcoal, with an Oregon State Board of Forestry bronze cap stamped: S 1/16 S9 S10 1950 199.</p> <p>from which:</p> <p>A fir snag, 6½ feet in diam., bears S 43° 30' E 64 lks, scribed: S 10 S 1/16 199.</p> <p>Placed a metal location poster on a 36 inch fir stub &amp; marked it: Sec 10 T1N R7W S 1/16 Cor 24 lks N 37° W.</p>
5249.7	<p>The corner to sections 9, 10, 15, &amp; 16 determined by the remains of an original bearing tree.</p>