CHAINS

RESTORED CORNER FOR THE OREGON STATE BOARD OF FORESTRY

November 14, 1951

The corner to sections 9, 10, 15, 16, Township 2 South, Range 7 West, W. M., Tillamook County, Oregon.

ORIGINAL

Post (now missing), from which a:

12" Hemlock bears N45 3/4E 38 lks; now a 12" stub badly burnt.

22" Hemlock bears N31 W 20 lks; now only the roots

20" Hemlock bears S26E 21 lks; now a 22" stub badly burnt.

50" Hemlock bears S75W 77 lks; now a 40" stub, badly burnt; scribe marks were visable when I was at this corner in 1947, since burnt out.

RESTORED CORNER & BEARING TREES

At the point for corner

Set a 15" x 36" galvenized iron pipe with 3" bronze cap marked, "OREGON STATE BOARD OF FORESTRY T2S R7W S9 S10 S16 S15 1951 142" 25 ft. in the ground, from which a:

48" Fir stump bears N75W 96 lks; scribed T2S R7W S9 BT 142.

66" Fir stump bears N32E 24 lks; scribed T2S R7W S10

44* Fir stump bears S59E 169 lks; scribed T2S R7W S15 BT 142.

64* Fir stump bears SO3W 24 lks; scribed T2S R7W S16 BT 142.

(Distances measured from center of bearing trees).

Nailed a metal location poster on the 64" Fir stump BT & marked it: Sec 16 T2S R7W Sec Cor 20 1ks NOSE.

REGISTERED OREGON LAND SURVEYOR

Restored by

WALTER M. ROBERTSON 142

Walter M. Robertson

Present & Witnessed by

Don Davis Asst. Forest Engineer OSBF

Present & Witnessed by

CONTRACTOR

BOOK 2